

PROJECT

Installation of Floor Tiles Rm 209, Floor and Wall Tiles @ CR Tiles @ CR Ground Floor (DORAC)

LOCATION

: VSU, Main Campus, VISCA, BAYBAY CITY, LEYTE

AMOUNT

: Php 103,350.00

DATE OF


INSPECTION:

Item No.	Work Description	Remarks
	Scope of Work:	
Fabrication and Installation		
1.00	Installation of Floor Tiles @ Rm 209	
	Clearing of Laboratory	Completed
	Hauling of Construction Materials	Completed
	Floor Setting	Completed
	Installation of Floor Tiles (0.60m x 0.60m)	Completed
2.00	Labor Services for Installation of Floor & Wall Tiles @ CR Ground Floor	
	Clearing of CR	Completed
	Hauling of Construction Materials	Completed
	Floor Setting	Completed
	Installation of Floor and Wall Tiles	Completed

Recommendation:


None

Inspected and conforme by:



JIEN APRIL JUALO

Civil Engineer-OVPPRGAS

Conforme:


PHLOEM D. GALUPO

Engineer III-PPO


ELVIN A. CABAÑERO
Architect , OVPPRGAS

Noted by:

DANIEL LESLIE S. TAN

Chairman, Inspectorate Team

PROJECT

Slicing of Fallen Trees (Typhoon Yolanda) and Hauling

LOCATION

: VSU, Main Campus, VISCA, BAYBAY CITY, LEYTE

AMOUNT

: Php 69,000.00

DATE OF


INSPECTION:

Item No.	Work Description	Remarks
	Scope of Work:	
	Slicing of Fallen Trees (Typhoon Yolanda)	Completed

Recommendation:


None

Inspected and conforme by:



JIEN APRIL JUALO

Civil Engineer-OVPPRGAS

Conforme:


PHLOEM D. GALUPO

Engineer III-PPO


ELVIN A. CABAÑERO

Architect , OVPPRGAS

Noted by:

DANIEL LESLIE S. TAN

Chairman, Inspectorate Team

PROJECT : **Repair of Blackboards, CHB Lab Partitions and Leaking Roof , DOPAC**

LOCATION : **VSU, Main Campus, VISCA, BAYBAY CITY, LEYTE**

AMOUNT : **Php 98,250.00**


DATE OF
INSPECTION:

Item No.	Work Description	Remarks
	Scope of Work:	
1.00	Repair of 7 Units Blackboard	Completed
2.00	Lab CHB Partitions including Plastering, Painting, Doors and Windows	Completed
3.00	Lab CHB Partitions including Plastering, Painting, Doors and Windows REPAIR OF LEAKING ROOF	Completed

Recommendation:


None

Inspected and conforme by:



JIEN APRIL JUALO

Civil Engineer-OVPPRGAS

Conforme:


PHLOEM D. GALUPO

Engineer III-PPO


ELVIN A. CABAÑERO

Architect , OVPPRGAS

Noted by:

DANIEL LESLIE S. TAN

Chairman, Inspectorate Team

PROJECT

Concreting of Service Road at Main Entrance. New Library

LOCATION

: VSU, Main Campus, VISCA, BAYBAY CITY, LEYTE

AMOUNT

: Php ~~69,000.00~~ 408,000.00

DATE OF

December 14, 2021

INSPECTION:

Item No.	Work Description	Remarks
	Scope of Work:	
	Concreting of Service Road at Main Entrance	
1.00	Lay-out and Road Clearing	completed
2.00	Installation of forms	completed
3.00	Sub-base Preparation	completed
4.00	Compacting	completed
5.00	Pouring of Concrete	completed
6.00	Removal of Forms	completed

Recommendation:

Inspected and conforme by:

JIEN APRIL JUALO

Civil Engineer-OVPPRGAS

Conforme:

PHLOEM D. GALUPO

Engineer III-PPG

ELVIN A. CABAÑERO

Architect, OVPPRGAS

Noted by:

DANIEL LESLIE S. TAN

Chairman, Inspectorate Team

PROJECT

Concreting of Road Service at Main Entrance , New Library

LOCATION

: VSU, Main Campus, VISCA, BAYBAY CITY, LEYTE

AMOUNT

: Php 178,000.00

DATE OF


INSPECTION:

Item No.	Work Description	Remarks
	Scope of Work:	
Concreting of Service Road at Main Entrance		
1.00	Layout and Road Clearing	
2.00	Installation of Forms	Completed
3.00	Sub-base Preparation	Completed
4.00	Compacting	Completed
5.00	Pouring of Concrete	Completed
6.00	Removal of Forms	Completed


Recommendation:


None

Inspected and conforme by:


JIEN APRIL JUALO
Civil Engineer-OVPPRGAS

Conforme:


PHLOEM D. GALUP
Engineer III-PPO


ELVIN A. CABAÑERO
Architect , OVPPRGAS

Noted by:

DANIEL LESLIE S. TAN
Chairman, Inspectorate Team

PROJECT

Repair of Animal Science Building

LOCATION

: VSU, Main Campus, VISCA, BAYBAY CITY, LEYTE

AMOUNT

: Php 237,400.00

DATE OF


INSPECTION:

Item No.	Work Description	Remarks
	Scope of Work:	
Repair of Animal Science Building		
1.00	Repainting of Roof	
2.00	Repainting of Classrooms, Lab rooms, External Walls, Cr Hallways, Hallway Exterior Ceiling, Doors, Windows not included	Completed
3.00	Repair and Animal Lab	Completed
4.00	Removal of Damaged Partitions	Completed
5.00	Filling of CHB Partitions with counters including plastering	Completed
6.00	Repair of Ceiling	Completed
7.00	Repair of Floor Tiles	Completed
8.00	Repair of break up Rooms Folding Partitions	Completed


Recommendation:


None

Inspected and conforme by:


JIEN APRIL JUALO
Civil Engineer-OVPPRGAS

Conforme:


PHLOEM D. GALUPO
Engineer III-PPO


ELVIN A. CABAÑERO
Architect, OVPPRGAS

Noted by:

ELVIN A. CABAÑERO

PROJECT : Construction of lights & sound Control Rm, VSU GYM
LOCATION : VSU, Main Campus, VISCA, BAYBAY CITY, LEYTE
AMOUNT : Php 74,250.00
DATE OF
INSPECTION:

Item No.	Work Description	Remarks
	Scope of Work:	
	Construction of <u>Lights & Sounds Control Room</u>	
1.00	RC Columns	Completed
2.00	RC Beams	Completed
3.00	RC Slabs	Completed
4.00	Filling of CHB including Plastering	Completed
5.00	Concrete Flooring	Completed

Recommendation:

None

Inspected and conformed by:

JIEN APRIL JUALO
Civil Engineer-OVPPRGAS

Conforme:

PHLOEM D. GALUPO
Engineer III-PPO

ELVIN A. CABAÑERO
Architect, OVPPRGAS

Noted by:

DANIEL LESLIE S. TAN
Chairman, Inspectorate Team


PROJECT : Construction of CHB Enclosure and Railings, VSU GYM
LOCATION : VSU, Main Campus, VISCA, BAYBAY CITY, LEYTE
AMOUNT : Php 210,500.00
DATE OF INSPECTION:

Item No.	Work Description	Remarks
	Scope of Work:	
	Construction of CHB enclosure and Railings including:	
1.00	Plastering	Completed
2.00	Hauling of Construction Materials	Completed
3.00	Wall Footings	Completed
4.00	Filling of CHB including plastering with plain cement finish	Completed
5.00	Concrete Flooring Stock Rooms	Completed
6.00	Fabrication of Doors and Jambs 2 units, Stockrooms	Completed


Recommendation:


None

Inspected and conforme by:


JHEN APRIL JUALO
Civil Engineer-OVPPRGAS

Conforme:


PHLOEM D. GALURO
Engineer III-PPO


ELVIN A. CABAÑERO
Architect , OVPPRGAS

Noted by:

DANIEL LESLIE S. TAN
Chairman, Inspectorate Team


PROJECT : Complete of COA Stockroom
LOCATION : VSU, Main Campus, VISCA, BAYBAY CITY, LEYTE
AMOUNT : Php 77,250.00
DATE OF INSPECTION:

Item No.	Work Description	Remarks
	Scope of Work:	
1.00	Hauling of Construction Materials	Completed
2.00	Installation of Ceiling Frames and Boards	Completed
3.00	Filling of CHB including Plastering (Exterior Only) @ Ground Floor CR Alumni	Completed
4.00	Repainting	Completed


Recommendation:


None

Inspected and conforme by


JHEN APRIL JUALO
Civil Engineer-OVPPRGAS

Conforme:


PHLOEM D. GALUPO
Engineer III-PPO


ELVIN A. CABAÑERO
Architect , OVPPRGAS

Noted by:

DANIEL LESLIE S. TAN
Chairman, Inspectorate Team


PROJECT : Fabrication and Installation of Steel Doors, G.I Pipe Railings and Window Grills
LOCATION : VSU, Main Campus, VISCA, BAYBAY CITY, LEYTE
AMOUNT : Php 44,250.00
DATE OF INSPECTION:

Item No.	Work Description	Remarks
	Scope of Work:	
Fabrication and Installation		
1.00	Hauling of Construction Materials	Completed
2.00	Fabrication and Installation of Main Steel Doors 4 units	Completed
3.00	Installation of G.I Pipe Railings	Completed
4.00	Fabrication of Installation of Window Grills	Completed
5.00	Painting (Primer Only)	Completed


Recommendation:


None

Inspected and conforme by:


JIEN APRIL JUALO
Civil Engineer-OVPPRGAS

Conforme:


RHLOEM D. GALUPO
Engineer III-PPO


ELVIN A. CABAÑERO
Architect , OVPPRGAS

Noted by:

DANIEL LESLIE S. TAN
Chairman, Inspectorate Team