



OFFICE OF THE DIRECTOR FOR PHYSICAL PLANT

Visca, Baybay City, Leyte, PHILIPPINES Telefax: 1041(LOCAL) Email: www.ppo.@vsu.edu.ph Website: www.vsu.edu.ph

REPAIR AND MAINTENANCE REQUEST

Filled in by req	uesting party	1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	Filled in by PPC)	
Date filed Building/Facilit House No/	Facility/		Date received	:	
Apartment No. Department Location		f admin Bldg	Received by Designation/	Na	me & Signature
Requesting pa	arty : EDUARDO	O. MANGAOANG & Signature	Position Maintenance control number	:	
Designation/ Position	:				
Please check an	nd specify the nature of wo	rk requested			
 □ Vehicle Repair □ Welding Works □ Machining works (lathe, shaper, drill press, etc.) 		☐ Plumbing	& Furniture Works Works tation equipment ory instrument	☐ Electrical W ☐ Heating, Veconditioning ☐ Others (spe	entilating, Air g & Refrigeration
	noline/Parte	☐ Available		☐ Not Avail	able
Materials/Sup	pries/raits.	Brief Description	of Repair and Maintena	nce	
Request for ar	n immediate check-up/ i eavy rainfalls.		of Repair and Maintena		ı to prevent rainwater
Request for ar flows during he	n immediate check-up/ i eavy rainfalls.	repair of RCCRDC C		floor upstairs area	to prevent rainwater
Request for ar flows during he	n immediate check-up/ i eavy rainfalls. PO personnel	repair of RCCRDC C	Ceiling located at second	floor upstairs area	
Request for ar flows during he	n immediate check-up/ i eavy rainfalls. PO personnel	Manpowe	Ceiling located at second	floor upstairs area	nours/days to finished
Request for ar flows during he Filled in by PF Part/Supplies	n immediate check-up/ reavy rainfalls. PO personnel s/Materials Required	Manpower Filled in	er Requirement	Estimated I	nours/days to finished
Request for ar flows during he Filled in by PF Part/Supplies	n immediate check-up/ reavy rainfalls. PO personnel s/Materials Required	Manpower Filled in	ceiling located at second er Requirement by the requesting party after service Satisfaction Not Satisfied	Estimated I	nours/days to finished
Request for ar flows during he	n immediate check-up/ reavy rainfalls. PO personnel s/Materials Required	Manpower Filled in sure)	ceiling located at second er Requirement by the requesting party after service Satisfaction Not Satisfied Slightly Satisfied Moderately Satisfied Very Satisfied	Estimated I	nours/days to finished pair and maintenance R-ALL RATING 2 Fair 4 Very Good