HEAVY EQUIPMENT & LIGHT VEHICLE MAINTENANCE UNIT Visca, Baybay City, Leyte

OFFICE PERFORMANCE COMMITMENT & REVIEW (OPCR)

I, Marlon G. Burlas, Head, HELVMU, commits to deliver and agree to be rated on the attainment of the following targets in accordance with the indicated measures for the period July to December, 2017.

Date:

MFO Descrip- tion	Success/Performance Indicator (PI)	Units/Persons Responsible	Target	Actual Accom- plishment		F	Rating		Remark
					Quality	Efficiency	Tjmeliness	Average	
UMFO 6: Gen	eral Administration and Support S	ervices							
HELVMU MFC	1. Administrative and Facilitative	Services							
PI 1: Number of letter and standard government forms preparation		R. M. Sanico, E. Dargantes	2,000	2,079	5	5	5	5.00	. HELVMU Office
THE RESERVE THE PARTY OF THE PA		E. Dargantes	500	520	5	4	4	4.33	. HELVMU Office
PI 3: No. of spare parts & lubricants record on stock cards		E. Dargantes	200	245	5	4	4	4.33	. HELVMU Office
P1 4: No. of do No. of building maintained	oors and windows opened s/surroundings cleaned & epaired & maintain	R. M. Sanico; M. Estrosas & JO's	40	43	5	5	5	5.00	. HELVMU Office & motorpool bldg
P1 5: No. of materials inspe	notor spare parts, lubricants & waste ected	R. M. Sanco	700	750	5	4	4	4.33	, Office & department concern
21 6: No. of C abricated	hristmas Characters repaired;	R. M. Sanico & JO's	40	45	5	5	5	5,00	. HELVMU Shop

P2 1: No. of grounds (sites) filled-up, scraped, cleared and improved	R. M. Sanico; B. Castanas; 2JO's	10	10	5	5	5	5.00	. Sepak Takraw court; Geodetic Engr. Bld., DFST bldg.; Labra Cottage; Climate change bldg., Spill Way (Animal Sci.); Const of VSU Perimeter Fence)
P2 2: No. of areas maintained	R. M. Sanico; 4 JO's	5	6	5	5	5	5.00	. Oval (Upper & Lower); F & G show area; Highway P. Fence & Borders; GSD surroundings & Beach area
HELVMU MFO 3. Ground Maintenance								
P3 1: No. of irrigation and drainage canals maintained	B. Castanas; & 4JO's	5	6	5	5	5	5.00	. Nangka & Mabolo Drive; Calbiga-a & Pangasugan; Expt'l. area; Beach & Highway area
P3 2: NO. of perimeter fence/gates fabricated & maintained	N. Manla; 3 JO's	4	5	5	5	4	4.67	. GSD; Highway P. Fence; F & G show area; VSU Garden Resort; Guard Post 1 & 2; Nangka & Mabolo Drive
HELVMU MFO 4. Land Preparation (Research	Related)					Victoria de la		
P4 1: No. of land areas prepared based on Job Request	R. M. Sanico; B. Castastanas; 2 JO's	9	9	5	4	4	4.33	. PhilRootscrops; NCRC; DPBG; DSS; Eco-FARMI; DAS DOH; Lac. High Sch. PCC
P4 2: No. of hauling/trips based on job request	B. Castanas; & 4JO's	200	250	5	5	5	5.00	. Research Center; Different departments/offices
HERVMU MFO 5. Repair of Heavy & Light Vel	nicles							
P5 1: No. of body repair & fabrication (Metal & Steel Work)s	R. M. Sanico; N. Manla; E. Orendain; 2JO's	10	15	5	5	4	4.67	. Jitney Passenger (3 units); Isuzu Elf 350; & 250; Mit. Pajero; Hi-Ace (Tolosa); DH- 100); Ford Tractor
P5 2: No. of under chassis repair, welding & servicing	A. Armada; R. Muana; C. Albiso; E. Orendain; M. Estrosas; 2 JO's	12	15	5	5	5	5.00	. Heavy and Light Vehicles repaired; and mantaned: light vehicles (13units); Trucks & Buses (10units); heavy and Farm Equipment (13units)

P5 3: No. of engine tune up; electrical repair & servicing	R. Muana; C. Albiso; R. Oracion; A. Armada; 1JO	70	75	5	5	5	5.00	. These include other deparments vehicles/equipment repaired & serviced by HELVMU	
P5 4: No. Transmission/Differential repair	A. Armada; R. Muana; B. Castanas; C. Albiso; 2JO's	6	6	5	5	5.	5.00		
P5 5. No. of engine overhauling/changing	A. Armada; R. Muana; E. Orendain; 1JO	5	6	5	5	5	5.00		
P5 6: No. of motor rewinding & electrical repair	R. Oracion	36	40	5	5	5	5.00	. Heavy & light vehicles repaired and maintained these includes other departments	
P5 7: No. of spare parts machining & fabrication	V. Meliton	68	80	5	5	5	5.00	. These include other dept. vehicles/eqpt. Repaired & serviced by HELVMU	
P5 8: No. of repainting of vehicles & equipment	3 JO's	5	7	5	5	5	5.00	. Jitney Passenger (3 units); Toyota Hi-Ace(Tolosa); isuzu Elf 250; Ford Tractor; Backhoe	
P5 9: No. of tire change & vulcanize	M. Estrosas; 1JO	260	265	5	5	5	5.00	. Based on job requests; all GSD vehicles & farm equipment	
P5 10: No. of steering (Power/Manual) & hydraulic pump repair	A. Armada; R. Muana; 1JO	1	5	8	5	5	6.00	. Bus 36; Fire truck; Backhoe; Jeep(2); Tractor (2); Dumpt Truck (2); L-200	
P5 11: No. of shop services based on job requests		40	45	5	5	5	5.00	. Job Requests/Job order	
HELVMU MFO 6. Operation and maintenance of	of vehicle								
P6 1: No. of trips served	Marlon G. Burlas; I. Laplana; N. Rabanos; C.							. GSD assigned vehicles including other department	
	Cutamora; A. Borneo; Charlito Rabanos; Nony Piad, Jr.; A.	1225	1248	5	5	4	4.67		
	Banayag; N. Quimco								

A. Armada; R. Muana; C. Albiso; N. Manla; E. Orendain; M. Estrosas, 3 JO's	36	36	5	5	5	5.00	. Light veh. (13 units); Trucks & Buses (10units); Heavy & Farm eqpt. (13 units); these also include other dept. vehicles/eqpt. Repaired & serviced by HELVMU
					П		. HELVMU Office
Zero percent complaint from clients served	90	95	5.0	5.0	5.0	5.00	. FILLEYMO SIMSE
						127.33	7.7
			0.00	0.00	0.00	4.90	
	Muana; C. Albiso; N. Manla; E. Orendain; M. Estrosas, 3 JO's Zero percent complaint from	Muana; C. Albiso; N. Manla; E. 36 Orendain; M. Estrosas, 3 JO's Zero percent complaint from 90	Muana; C. Albiso; N. Manla; E. 36 Orendain; M. Estrosas, 3 JO's Zero percent complaint from 90 95	Muana; C. Albiso; N. Manla; E. Orendain; M. Estrosas, 3 JO's Zero percent complaint from clients served 90 95 5.0	Muana; C. Albiso; N. Manla; E. 36 36 5 5 Orendain; M. Estrosas, 3 JO's Zero percent complaint from clients served 90 95 5.0 5.0	Muana; C. Albiso; N. Manla; E. Orendain; M. Estrosas, 3 JO's Zero percent complaint from clients served 90 95 5.0 5.0 5.0	Muana; C. Albiso; N. Manla; E. Orendain; M. Estrosas, 3 JO's Zero percent complaint from clients served 90 95 5.0 5.00 5.00 127.33

Calibrated by:	Recommending Approval:
June	May
REMBERTO A. PATINDOL	REMBERTO A. PATINDOL
Chairman, PMT	Vice Pres. for Admin. & Finance
Date:	Date:

Approved:

EDGARDO E. TULIN, Ph.D.

President

Date: