

Email: ovpaf@vsu.edu.ph

Website: www.vsu.edu.ph

Office of the Vice President for Administration & Tinance

TO:	Un. elizabeth	Guerroc		
_				

FOR:

[] Study

Comments/Recommendation

[ ] Appropriate Action [ ] Information

[]

[ ] Notation and Return [ ] Dissemination

REMARKS

PLEASE SUBMIT THE YELOUIDOD/ ETIMATED WIT OF RENWATUR.

DANIEL LESLIE S. TAN VP, Administration & Finance and Finance

proaching. However, the renovation of the e to lack of electrical manpower. In addition, ent room is still not done due to lack of funds. d in due time, it might again earn a Non-In this connection, I would like to aluation. ation of the DoPAC facilities.

**DEPARTMENT OF PURE & APPLIED CHEMISTRY** 

Visca, Baybay City, Leyte, PHILIPPINES

Telefax: +63 563 7747

Email: dopac@vsu.edu.ph Website: www.vsu.edu.ph

ction on this matter. Thank you very much.

ELIZABETH S. QUEVEDO

Recommending Approval:

MA. THERESA P. LORETO Dean, CAS

DANIEL LESLIE S. TAN VP for Admin. & Finance

Approved:

EDGARDO E. TULIN President

Visca, Baybay City, Leyte, PHILIPPINES Telefax: +63 563 7747 Email: dopac@vsu.edu.ph Website: www.vsu.edu.ph

November 24, 2022

Edgardo E. Tulin, PhD President Visayas State University

Thru: Daniel Leslie Tan

Vice President for Administration and Finance

The ISO external audit 2023 is fast approaching. However, the renovation of the weighing/balance room is still not completed due to lack of electrical manpower. In addition, the renovation of the dilapidated DoPAC instrument room is still not done due to lack of funds. If renovations will not be done and completed in due time, it might again earn a Non-Compliance result in the coming face to face evaluation. In this connection, I would like to make the request for funds for the prompt renovation of the DoPAC facilities.

Hoping for a prompt and an immediate action on this matter. Thank you very much.

Respectfully yours,

ELIZABETH S. QUEVEDO

Recommending Approval:

MA. THERESA P. LORETO

Dean, CAS

DANIEL LESLIE S. TAN VP for Admin. & Finance און און

Approved:

EDGARDO E. TULIN

President



Vision:



May 29, 2023

ELIZABETH S. QUEVEDO Dept Head, DOPAC Visca, Baybay City, Leyte

Dear Ma'am:

We thank you for your inquiry and would like to present the following cost estimate as per requested information: "Materials and Cost Estimation for the Repair of Laboratory Table Top in DoPAC AC-101 Rm", with reference service request no. BHM-23-098.

Cost estimate: (Kindly refer to the table shown below.)

No	Item Name	Qty.	Unit	Single price	Total price
1.	Marine Plywood 3/4	15	pcs		
2.	Stickwell				
3.	Finishing Nails # 2" and 1 1/2"	3	kgs		
4.	Cement	40	bags		
5.	Finishing Sand	6	Cu. M.		
6.	10mm Def. Bars	25	pcs		
7.	Tie Wire # 16	10	kgs		

Respectfully yours,

LUCIO O. POLE JR. BHM Foreman, PPO Noted by:

MARIO LILIO P. VALENZONA Director, PPO

Website: www.vsu.edu.ph Phone: +63 53 565 0600 Local 1041





