

by file copy

# VISAYAS STATE COLLEGE OF AGRICULTURE

Baybay, Leyte, Philippines

Office of the President



9 January 2001

MEMORANDUM NO. 04

Series of 2001

T O: Engr. Nestor M. Israel — AI-10

R E: Repair of Perimeter Fence

It has been noted that there are portions of the ViSCA perimeter fence which are damaged. In fact, some were intentionally damaged to provide short cut to many people. This situation poses a security problem to the College.

In view of this, you are hereby directed to institute measures to repair the damaged perimeter fence using salvage or existing materials of the PPO.

For compliance.

  
**PACIENCIA P. MILAN**  
President — pk

cc: Dr. N. P. Pascual  
ViSCA Security Force — m 1/10/01  
Records  
File — OURA 1/10/01