



VISAYAS STATE COLLEGE OF AGRICULTURE

Baybay, Leyte, Philippines

Office of the President

21 February 2000

MEMORANDUM NO. 36
Series of 2000

T O: Engr. Nestor M. Israel

SUBJECT: Unlighted Areas and Leaking Faucets

It has come to the attention of the undersigned that there are unlighted areas and leaking faucets within the ViSCA campus.

To prevent untoward incidents that might happen in critical areas during nighttime, you are hereby directed to check unlighted areas and install the necessary lighting facility if possible or replace unserviceable bulbs.

You are also directed to check leaking faucets in campus to prevent low water pressure in some areas.

For compliance.


PACIENCIA P. MILAN
President