

Visayas State College of Agriculture
Baybay, Leyte

OFFICE OF THE PRESIDENT

12 September 1997

Memorandum No. 84
Series of 1997

T O: Dr. Zosimo de la Rosa *his*
Engr. Nestor Israel *am*

R E: Proper Painting of Concrete Humps in Campus

With the unfortunate motor accident that happened recently due to an unpainted concrete hump, you are hereby directed to paint immediately all humps inside the campus. You are also advised to check and modify humps that are too high.

For your compliance.

Samuel S. Go
SAMUEL S. GO
President

cc: Dr. N. P. Pascual
Dr. R.C. Guarte
Ms. L. B. Cano
file

9/15/97