




05 June 2023

**Comfort Room Repair/Renovation/Construction Information Form**

Dept./Office/ Unit/Center	Contact Person & Email Address	Building	No. of CRs for Inspection	Remarks
ISRDS	Lilian B. Nuñez lilian.nunez@vsu.edu.ph	ISRDS Building	1 Female CR (Big) with: 2 toilet cubicles & 1 shower room	No PWD provision;  Water tank of 1 toilet not functional  Door of 2 cubicles damaged
			1 Male CR (Big) with: 2 urinals, 2 toilet cubicles, & 1 shower room	No PWD provision;  Flush of two urinals not functional
			1 Female CR (Small)	No PWD provision;  Poor flushing during rainy days
			1 Male CR (Small)	No PWD provision;  Poor flushing during rainy days
			Ramp construction	On left wing leading to Training Room & Gender Resource Center
			<b><u>Other Necessary Repairs</u></b>  Replacement of wooden parts of building damaged by rodents and insects  Rewiring of whole building	Request approved by Pres. EE Tulin

Prepared by:

  
**LILIAN B. NUÑEZ**  
Director, ISRDS

Noted by:

**DANIEL LESLIE S. TAN**  
Vice President-Administration &  
Finance