



OFFICE OF THE DIRECTOR FOR PHYSICAL PLANT

Visca, Baybay City, Leyte, PHILIPPINES Telefax: 1041(LOCAL) Email: www.ppo.@vsu.edu.ph Website: www.vsu.edu.ph

REPAIR AND MAINTENANCE REQUEST

Filled in by requesting party			Filled in by PPC		
Date filed : March 21, 2023			Date received	1	
Building/Facility/ House No/ Apartment No./ Department	ISRDS		Received by	Name & Signature	
Location : VSU, Visca, Baybay City		Designation/ Position	ž		
Requesting party : MERRY JEAN A. CAPARAS Name & Signature Designation/			Maintenance control number	:	
Position :	Instructor 1				
Please check and specify the nature of work requested					
☐ Vehicle Repair		Carpentry & Fu	urniture Works	☐ Electrical Works	
☐ Welding Works ☐ Plumbing Wor			cs	☐ Heating, Ventilating, Air	
☐ Machining works ☐ Plumbing works ☐ Conditioning & Refrigeration ☐ Conditioning & Refrigeration ☐ Conditioning & Conditionin					
(lathe, shaper, drill press, etc.) & Laboratory instrument					
Materials/Supplies/Parts: Available Not Available					
Brief Description of Repair and Maintenance					
Check and repair aircon unit at the Training room.					
Filled in by PPO personnel Part/Supplies/Materials Required Manpower R			auirom ant	Estimated hours/days to finished	
Part/Supplies/Materials Required Manpowe			quirement	Estimated hours/days to finished	
-					
k					
Conducted			the requesting party after the conduct of repair and maintenance		
by: PPO Personnel (Name & Signature) PPO Unit		Servic	e Satisfaction	OVER-ALL RATING	
		☐ 1. No	ot Satisfied	☐ 1 Poor ☐ 2 Fair	
PPO Unit		2. Sli	ightly Satisfied	☐ 3 Good ☐ 4 Very Good	
Checked &		3. Mo	oderately Satisfied	☐ 5 Excellent	
Verified by:	PPO Head	-	ery Satisfied	Comments & Suggestion	
Ä	(Name & Signature)	□ 5. Ex	tremely Satisfied		
		Name	and Signature		

Vision: Mission: