

OFFICE OF THE DIRECTOR FOR PHYSICAL PLANT

Visca, Baybay City, Leyte, PHILIPPINES Telefax: 1041(LOCAL) Email: www.ppo.@vsu.edu.ph Website: www.vsu.edu.ph

REPAIR AND MAINTENANCE REQUEST

Filled in by requesting party		Filled in by PP	0
Date filed : Janua	ry 5, 2022	Date received	:
Building/Facility/			
House No/		Received by	
Apartment No./ Department AD	E 216		Name & Signature
Location		Designation/	Name & Olymature
Location	DBM)	Position	:
Requesting party : ANG		Maintenance	:
Requesting party PAR	ADERO	control number	
Designation/			
Position : INSTR	UCTOR III		
Note:			
i. Three (3) copies: (1) for ii. One (1) job request in ev	requesting party, (1)) for PPO unit Head &	(1) for maintenance team
iii. Job request control numi			
Please check and specify the nature of	work requested		
☐ Vehicle Repair		entry & Furniture	☐ Electrical Works
_	Works		
☐ Welding Works	☐ Plum	bing Works	Heating, Ventilating, Air conditioning & Refrigeration
(lathe shaper drill press etc.) equipme		ımentation	
			Others (specify):
(latile, shaper, and press, etc.)	& Lab	oratory instrument	
Brief D	escription of P	Repair and Mainte	nanco
Dilei D	escription or it	tepan and manite	Hance
To Repair Doork	nob, Faucet at Fe	emale CR and Men's	Urination Bowl.
Materials/Supplies/Parts:	☐ Availab	le	☐ Not Available
material of appropriate.	/ (Valida)		LI NOT Available
Filled in by PPO personnel			
Part/Supplies/Materials	Mannaura	- Deswisses	Estimated hours/days to
Required	ivianpowe	r Requirement	finished
Inspected	Checked		Approved
by:	& Verified		by:
PPO Maintenance	by:	PPO Unit Head	PPO Director