

OFFICE OF THE DIRECTOR FOR PHYSICAL PLANT

Visca, Baybay City, Leyte, PHILIPPINES Telefax: 1041(LOCAL) Email: www.ppo.@vsu.edu.ph Website: www.vsu.edu.ph

REPAIR AND MAINTENANCE REQUEST

Filled in by requesting party		Filled in by PPC)
	18/2022	Date received	:
Building/Facility/			
House No/	RDC Office	Received by	
Apartment No./ Department			Name & Signature
	f admin bldg	Designation/	
. Dack of	admir blug	Position	
	muy f	Maintenance	:
Requesting partyEDUARDO	O. MANGAOANG	control number	
OSILIOIT	or, RCCRDC		
Note: i. Three (3) copies: (1) fo			(4) *
ii. One (1) job request in a		r PPO unit Head & ((1) for maintenance team
iii. Job request control nur	mber is required.		
Please check and specify the nature o	f work requested		
☐ Vehicle Repair	☐ Carpentry & Furniture Works		☐ Electrical Works
□ \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\			☐ Heating, Ventilating, Air
☐ Welding Works	Welding Works		conditioning & Refrigeration
☐ Machining works	☐ Instrume	entation	Others (specify):
(lathe, shaper, drill press, etc.	equipment	atory instrument	= oniors (speediy).
Brief	Description of Rep	pair and Mainte	nance
English to the book of			
Emergency repair of the broken f RCCRDC bldg	aucet bathroom sink	at Comfort Room	Male 2 nd floor training hall
TOOTED blug			
Materials/Supplies/Parts:	☐ Available		☐ Not Available
Filled in by PPO personnel			
Part/Supplies/Materials	Manpower F	Requirement	Estimated hours/days
Required	- manpower :	toquii omone	finished
In control	Observation 1		
Inspected	Checked		Approved
DV.			
PPO Maintenance	& Verified	PO Unit Head	by: