



REPAIR AND MAINTENANCE REQUEST

Filled in by requesting party	
Date filed	: May 24, 2022
Building/Facility/ House No/ Apartment No./ Department	: ISRDS
Location	: VSU, Visca, Baybay City
Requesting party	: <u>LILIAN B. NUÑEZ</u> Name & Signature
Designation/ Position	: <u>Director, ISRDS</u>

Filled in by PPO	
Date received	:
Received by	: _____ Name & Signature
Designation/ Position	:
Maintenance control number	:

Please check and specify the nature of work requested		
<input type="checkbox"/> Vehicle Repair	<input type="checkbox"/> Carpentry & Furniture Works	<input type="checkbox"/> Electrical Works
<input type="checkbox"/> Welding Works	<input type="checkbox"/> Plumbing Works	<input type="checkbox"/> Heating, Ventilating, Air conditioning & Refrigeration
<input type="checkbox"/> Machining works (lathe, shaper, drill press, etc.)	<input type="checkbox"/> Instrumentation equipment & Laboratory instrument	<input type="checkbox"/> Others (specify): _____

Materials/Supplies/Parts:

☐ Available

☐ Not Available

Brief Description of Repair and Maintenance
No water supply at the ISRDS comfort rooms and kitchen and some part of the faucet outside the building has slow drop of water.

Filled in by PPO personnel		
Part/Supplies/Materials Required	Manpower Requirement	Estimated hours/days to finished

Conducted by:	PPO Personnel (Name & Signature)
PPO Unit	
Checked & Verified by:	PPO Head (Name & Signature)

Filled in by the requesting party after the conduct of repair and maintenance	
Service Satisfaction <input type="checkbox"/> 1. Not Satisfied <input type="checkbox"/> 2. Slightly Satisfied <input type="checkbox"/> 3. Moderately Satisfied <input type="checkbox"/> 4. Very Satisfied <input type="checkbox"/> 5. Extremely Satisfied	OVER-ALL RATING <input type="checkbox"/> 1. - Poor <input type="checkbox"/> 2. - Fair <input type="checkbox"/> 3. - Good <input type="checkbox"/> 4. - Very Good <input type="checkbox"/> 5. - Excellent Comments & Suggestion _____ Name and Signature