



## OFFICE OF THE DIRECTOR FOR PHYSICAL PLANT Vices Backer City Laste

Visca, Baybay City, Leyte, Telefax: 1041 (LOCAL) Email: Website: www.vsu.edu.ph

## ANNUAL EQUIPMENT CALIBRATION PLAN NARC DIAGNOSTIC LABORATORY

	# Asset/Tag	Equipment/Instrument	Location				_		EAR: 2	YEAR: 2021	/EAR: <u>2021</u>	/EAR: <u>2021</u>	/EAR: 2021
NDL -1 Top Loading Balance NDL -2 Laminar Flow Hood	CT 1157				Mar		Apr	Apr May	Apr May Jun	Apr May Jun Jul	Apr May Jun Jul Aug	Apr May Jun Jul Aug Sep	Apr May Jun Jul Aug
NDL -2 Laminar Flow Hood		Top Loading Balance	NDL		$\bigvee$	$\triangle$	$\triangle$		X	X	X	X	X
	NDL -2	Laminar Flow Hood	NDL						X	X	X	X	X
5. 6. 6. 7. 7. 8. 8. 9.	4.												
6. 7. 7. 8. 8. 9. 9. 9. 9. 9. 9. 9. 9. 9. 9. 9. 9. 9.	Ċ												
7. 8. 8. 9. 10. 10. 10. 10. 10. 10. 10. 10. 10. 10	6.												
8. 9. 10.	7.												
9. 10.													
10.	9.												
	10.												

Reviewed and Approved by:	Prepared by:
Robelyn T. Piamonte	Darlene E. Ceriales Science Research Assistant
Date:	Date:
12/14/21	Date: 12/14/21
Legend	
Planned	

Completed

Vision: Mission: