



REPAIR AND MAINTENANCE REQUEST

Filled in by requesting party	
Date filed	: August 23, 2022
Building/Facility/ House No/ Apartment No./ Department	: Eco-FARMI
Location	: VSU, Visca, Baybay Leyte
Requesting party	: ODELO B. BALDOS
	Name & Signature
Designation/ Position	: <u>ASST. PROF. II</u>

Filled in by PPO	
Date received	:
Received by	: _____
	Name & Signature
Designation/ Position	:
Maintenance control number	:

Please check and specify the nature of work requested		
<input type="checkbox"/> Vehicle Repair	<input type="checkbox"/> Carpentry & Furniture Works	<input type="checkbox"/> Electrical Works
<input type="checkbox"/> Welding Works	<input type="checkbox"/> Plumbing Works	<input type="checkbox"/> Heating, Ventilating, Air conditioning & Refrigeration
<input checked="" type="checkbox"/> Machining works (lathe, shaper, drill press, etc.)	<input type="checkbox"/> Instrumentation equipment & Laboratory instrument	<input type="checkbox"/> Others (specify): _____
Materials/Supplies/Parts:		<input type="checkbox"/> Not Available
		<input type="checkbox"/> Available

Brief Description of Repair and Maintenance
● Repair of the brush cutter at the Eco-FARM, Demo Farm.

Filled in by PPO personnel		
Part/Supplies/Materials Required	Manpower Requirement	Estimated hours/days to finished

Conducted by: _____
PPO Personnel
(Name & Signature)

PPO Unit: _____

Checked & Verified by: _____
PPO Head
(Name & Signature)

Filled in by the requesting party after the conduct of repair and maintenance	
Service Satisfaction <input type="checkbox"/> 1. Not Satisfied <input type="checkbox"/> 2. Slightly Satisfied <input type="checkbox"/> 3. Moderately Satisfied <input type="checkbox"/> 4. Very Satisfied <input type="checkbox"/> 5. Extremely Satisfied	OVER-ALL RATING <input type="checkbox"/> 1. - Poor <input type="checkbox"/> 2. - Fair <input type="checkbox"/> 3. - Good <input type="checkbox"/> 4. - Very Good <input type="checkbox"/> 5. - Excellent Comments & Suggestion
Name and Signature	