

OFFICE OF THE DIRECTOR FOR PHYSICAL PLANT

Visca, Baybay City, Leyte, PHILIPPINES Telefax: 1041(LOCAL)

Email: www.ppo.@vsu.edu.ph Website: www.vsu.edu.ph

PHYSICAL PLANT SERVICE REQUEST FORM

Filled in by requesting	party	Filled in by PPO
Date filed :	February 21, 2022	Date received :
Building/Facility/ House No/		4
Apartment No./	G/F Admin. Building	Received by
Department	4	Name & Signature
Location	OHRA	Designation/
	011101	Position
Requesting party : M	IARIA ROBERTA S. MIRAFLOR	Maintenance : control number
Designation/ Position	Head, OHRA	
T. b	(1)	
To be accomplished in	n three (3) copies ecify the nature of service reque	
	plifier, speakers and	981
microphones)	pinier, speakers and	Tent installation/s
With Lights? Ye	s No	Setup Location:
Setup Location:	eded:	No. of tent:
		l ent size:
Estimated Durat	ion (hrs):	Fabrication/s (new cabinets, furniture, metal works and other fabrications not considered as repair and
Land preparation,	plowing & harrowing	maintenance)
Location/Area co	vered:	Installation/s (tarpaulin, signage, new lock & knobs &
Estimated passin	g trip:	other installation not considered as repair and maintenance)
Site development, backfilling	levelling, scrapping &	Machining works (lathe, shaper, drill press & etc.)
Location:		Others (specify):Installation of electrical outlet
	tion materials, office	Others (specify). Installation of electrical outlet
equipment & etc.)	tion materials, office	
	To:	
	Brief Description	of Service Request
		or our request
To install addition	onal electrical outlets	
		120
Service Conducted by	:	
octvice conducted by	Name & Signature	To be filled by the requesting party after
ODO Unit		service request conducted
PPO Unit		Overall Service Satisfaction
Conformed by		Not Satisfied
Requesting Party)	:	— Hot datisfied
	Name & Signature	2. Slightly Satisfied
Checked by		3. Moderately Satisfied
PPO Unit Head)	:	
,	Name & Signature	4. Very Satisfied
		5. Extremely Satisfied