

OFFICE OF THE DIRECTOR FOR PHYSICAL PLANT

Visca, Baybay City, Leyte, PHILIPPINES Telefax: 1041(LOCAL) Email: www.ppo.@vsu.edu.ph Website: www.vsu.edu.ph

REPAIR AND MAINTENANCE REQUEST

Filled in by requesting party		Filled in by PPO		
	per 28, 2021	Date received	:	
Location : ANALITA Requesting party : ANALITA Designation/ Position : PROF	tment 68 A. SALABAO FESSOR I	Received by Designation/ Position Maintenance control number	:	Name & Signature
 i. Three (3) copies: (1) for requesting party, (1) for PPO unit Head & (1) for maintenance team ii. One (1) job request in every of PPO unit 				
iii. Job request control number is required.				
Please check and specify the nature of	work requested			
☐ Vehicle Repair				
☐ Welding Works	☐ Plumbing Works		☐ Hear	ting, Ventilating, Air ditioning & Refrigeration
☐ Machining works (lathe, shaper, drill press, etc.) ☐ Instrumentation equipment & Laboratory instrument			9	ers (specify):
Prist Description of the Control of				
Brief Description of Repair and Maintenance				
ELECTRICAL CONNECTION.URGENT!				
Materials/Supplies/Parts:	☐ Available			Not Available
Filled in by PPO personnel				
Part/Supplies/Materials Required	Manpower	Requirement	Estim	nated hours/days to finished
Inspected by:	Checked & Verified		Approve	d
PPO Maintenance	by: PPO Unit Head PPO Director			PPO Director