



## OFFICE OF THE DIRECTOR FOR PHYSICAL PLANT

Visca, Baybay City, Leyte, PHILIPPINES Telefax: 1041(LOCAL) Email: www.ppo.@vsu.edu.ph Website: www.vsu.edu.ph

## REPAIR AND MAINTENANCE REQUEST

Filled in by requesting party		Filled in by PPC	)		
Date filed : Ju	ne 27, 2022	Date received	:		
•	ed Research and vation Center	Received by	Nam	e & Signature	
	: Upper Campus, VSU Main		:		
Requesting party : DILBERTO O. FERRAREN  Name & Signature  Designation/ . VP for Planning, Resource		Maintenance control number	:		
	n, and Aux. Services				
Please check and specify the nature of v	vork requested				
☐ Vehicle Repair ☐ Welding Works	Furniture Works	☐ Electrical Wo	tilating, Air		
Machining works (lathe, shaper, drill press, etc.)	ion equipment instrument	equipment			
Materials/Supplies/Parts:  Available  Not Available					
Brief Description of Repair and Maintenance					
Popped-up/ buckled/ tented tiles.					
Filled in by PPO personnel					
		Requirement	Estimated hours/days to finished		
Conducted —	Filled in by	Filled in by the requesting party after the conduct of repair and maintenance			
by. PPO Person		vice Satisfaction	OVER-ALL RATING		
PPO Unit	ature) □ 1. I	Not Satisfied	☐ 1 Poor	☐ 2 Fair	
Checked &	2. 3	Slightly Satisfied	☐ 3 Good	☐ 4 Very Good	
Verified by:	<u> </u>	Moderately Satisfied	☐ 5 Excellent		
PPO Head (Name & Signa	.4	Very Satisfied  Extremely Satisfied	Comments & Suggestion		
	<u> </u>	Extremely Galished			
	Nam	ne and Signature			

Vision: Mission: