



PROJECT : Construction of Stockroom Accounting
 LOCATION : VSU, Main Campus, VISCA, BAYBAY CITY, LEYTE
 AMOUNT : Php 73,500.00
 DATE OF INSPECTION: Dec. 3, 2021

Item No.	Work Description	Remarks
	Scope of Work:	
1.00	Construction of Stockroom	
	Removal of Existing Structures	completed
	Hauling of Construction Materials	completed
	Filling of CHB	completed
	Cement Plastering	completed
	Painting	completed
	Installation of Doors and Windows	completed
		- not in the picture is the installation of wooden window (not in Purchase Request what material used for Window)

Recommendation:


Pakyaw Contractors should attach on-going construction photos, so inspectors can identify which , and where to inspect.

Inspected and conforme by:


JIEN APRIL JUALO
 Civil Engineer-OVPPRGAS

Checked by:


PHLOEM D. GALUPO
 Engineer III-PPO


ELVIN A. CABAÑERO
 Architect , OVPPRGAS

Conforme :

 End User - Accounting Head

Noted by:

DANIEL LESLIE S. TAN
 Chairman, Inspectorate Team