



OFFICE OF THE DIRECTOR FOR PHYSICAL PLANT

Visca, Baybay City, Leyte, PHILIPPINES

Telefax: 1041(LOCAL) Email: www.ppo.@vsu.edu.ph Website: www.vsu.edu.ph

REPAIR AND MAINTENANCE REQUEST

Filled in by requesting party				Filled in by PPC)	
Date filed : Building/Facility/	Date filed : September 13, 2 Building/Facility/			Date received		
House No/ Apartment No./ Department	PSB Room DA-01 and DA-02			Received by		Name & Signature
Location :	VSU, Upper Campus Abigait . Amarill			Designation/ Position Maintenance	:	
Designation/ . Position	Nan	ne & Signature SRA		control number		
Please check and specia	fy the nature of w	ork requested				
☐ Vehicle Repair ☐ Welding Works ☐ Machining works (lathe, shaper, dri	☐ Plum	bing Works umentation e poratory inst	equipment	☐ Electrical Works ☐ Heating, Ventilating, Air conditioning & Refrigeration ☐ Others (specify): ☐ Not Available		
1. Ligi	hts and Ceiling	Brief Descript		air and Maintenar	nce	
Filled in by PPO pers	onnel					
Part/Supplies/Materials Required		Man	Manpower Requirement		Estimated hours/days to finished	
		Fi	lled in by the	requesting party afte	r the conduct of	of repair and maintenance
Conducted ———by:	PPO Personr		Service Satisfaction		OVER-ALL RATING	
PPO Unit	(Name & Signature)			Satisfied ntly Satisfied	☐ 1 Poor	
Checked & Verified by: PPO Head (Name & Signature)			4. Very	erately Satisfied Satisfied	☐ 5 Excellent Comments & Suggestion	
		ture)	□ 5. Extremely Satisfied Name and Signature			

Vision:

Mission:

A globally competitive university for science, technology, and environmental

conservation.

Development of a highly competitive human resource, cutting-edge scientific knowledge and innovative technologies for sustainable communities and environment.

Page 1 of 1 FM-PPO-09 v0 02-28-2022