



## OFFICE OF THE DIRECTOR FOR PHYSICAL PLANT

Visca, Baybay City, Leyte, PHILIPPINES Telefax: 1041(LOCAL) Email: www.ppo.@vsu.edu.ph Website: <u>www.vsu.edu.ph</u>

## **REPAIR AND MAINTENANCE REQUEST**

Filled in by requesting	ng party			Filled in by PPO				
Date filed : 17 March 2022			Ī	Date received	:			
Building/Facility/ House No/ Apartment No./ Department	:			Received by		Name 8	& Signature	
Location :			Designation/ Position		:			
Requesting party	: CHARLIE S. A			Maintenance control number	:			
Designation/ Position	: Head, DM							
Please check and spec	cify the nature of work reques	ted						
☐ Vehicle Repair ☐ Carpentry & F				furniture Works				
<ul> <li>□ Welding Works</li> <li>□ Machining works</li> <li>□ (lathe, shaper, drill press, etc.)</li> <li>□ Plumbing Wo</li> <li>□ Instrumentation</li> <li>&amp; Laboratory</li> </ul>				quipment	<ul><li>Heating, Ventilating, Air conditioning &amp; Refrigeration</li><li>Others (specify):</li></ul>			
(latile, shaper, drill press, etc.)				ument	Repainting of the head's office table			
Materials/Supplies/Parts: Available						Not Available		
Brief Description of Repair and Maintenance								
One (1) book shelve One (1) book shelve	ets for the Department of Ne for the room of the department of the laboratory room of the for the laboratory room of the for the mini kitchen of t	rtment head. f Meteorology	fice (	of Meteorology				
Filled in by PPO per	sonnel							
		Manpower R	Manpower Requirement			Estimated hours/days to finished		
		Filled in by the requesting party after the conduct of repair and maintenance						
Conducted ———by:	PPO Personnel	Servi	Service Satisfaction		OVER-ALL RATING			
	(Name & Signature)	□ 1. N	lot S	atisfied		I Poor	☐ 2 Fair	
PPO Unit		_	Slight	ntly Satisfied		3 Good	☐ 4 Very Good	
Checked & Verified by:		□ 3. N	/lode	erately Satisfied		5 Excellent		
	PPO Head		-	Satisfied	Comments & Suggestion			
	(Name & Signature)	□ 5. E	xtre	remely Satisfied				
		Nam	e an	d Signature				