

OFFICE OF THE DIRECTOR FOR PHYSICAL PLANT

Visca, Baybay City, Leyte, PHILIPPINES Telefax: 1041(LOCAL) Email: www.ppo.@vsu.edu.ph Website: www.vsu.edu.ph

REPAIR AND MAINTENANCE REQUEST

		0
equesting party MARK ANTHO Pesignation/ Position INSTRUCTO	Received by OF SOIL SCIENCE Designation/ Position Maintenance control number OR requesting party. (1) for PPO unit Heal very of PPO unit	
lease check and specify the nature of w	ronk requested	
☐ Vehicle Repair ☐ Welding Works	☐ Carpentry & Furniture Works ☐ Plumbing Works ☐ Instrumentation	☐ Electrical Works ☐ Heating, Ventilating, Air conditioning & Refrigeration
Machining works (lathe, shaper, drill press, etc.)	equipment & Laboratory instrumer	
(lathe, shaper, drill press, etc.) Brief De	equipment & Laboratory instrumer ascription of Repair and Mair	nt stemance
(lathe, shaper, drill press, etc.)	equipment & Laboratory instrumer ascription of Repair and Mair	nt stemance
(lathe, shaper, drill press, etc.) Brief De Five (5) Damoged fauce Materials/Supplies/Parts:	equipment & Laboratory instrumer **scription of Repair and Main ts; Leakage (Sink) - City	itenance ECK AND REPAIR Not Available
(lathe, shaper, drill press, etc.) Brief D Five (5) Dameged fouce	equipment & Laboratory instrumer **scription of Repair and Main ts; Leakage (Sink) - City	Menance ECK AND REPAIR
(lathe, shaper, drill press, etc.) Brief De Five (5) Dameged fouce Materials/Supplies/Parts: Filled in by PPO personnel Part/Supplies/Materials	equipment & Laboratory instrumer escription of Repair and Mair ts; Leakage (Sink) - City Available	Not Available Estimated hours/days to