



PHYSICAL PLANT OFFICE

Visca, Baybay City, Leyte, PHILIPPINES Telefax: 1041(LOCAL) Email: www.ppo.@vsu.edu.ph

Website: www.vsu.edu.ph

REPAIR AND MAINTENANCE REQUEST

REQUEST INFORMATION			
Filled in by requesti		Filled in by PPO	
Date filed	: May 21, 2025	Date received :	
Building/Departm	<u> </u>	Received by Name & Signature	
Location	: ISRDS Munus	Designation/Position :	
Requesting party	: LILIAN B. NUÑEZ Name & Signature	Request Reference : Number	
Designation/Posit	ion : Director		
Contact no./Emai	· :		
Please check and specify the nature of work requested:			
☐ Vehicle Repair ☐ Carpentry & Furniture Works ☐ Electrical Works			
☐ Welding Works ☐ Plumbing Works ☐ Heating, Ventilating, Air conditioning & Refrigeration			
☐ Machining works (Lathe, shaper, drill press, etc.) ☐ Instrumentation equipment & Laboratory instrument ☐ Others (specify in the brief description below)			
Brief Description of the Nature of Work Requested			
Repair and replacement of the broken and cracked tiles at the ISRDS classroom. and corridor.			
INSPECTION (Filled in by PPO Personnel)			
Date of Inspection: Time started: [AM] [PM] Time ended: [AM] [PM]			
☐ In-House Repair and Maintenance ☐ For Outsourcing Repair and Maintenance			
Materials/Parts Manpower Required:		Estimated hours/days	
☐ Available	Available	Schedule of repair:	-
Not Available Not Available			
Conducted:		Confirmed:	
PP	O Maintenance Personnel/Name & Sign	Name and Signature	
	Designation/Position	Designation/Position	
ACCOMPLISHM			
		Filled in by Requesting Party	
Conducted :	PPO Maintenance Personnel	Service Satisfaction OVER ALL RATING	
Date & Time		☐ 1. Not Satisfied ☐ 1. Poor ☐ 2. Fair ☐ 2. Slightly Satisfied ☐ 3. Good ☐ 4. Very ☐ 3. Moderately Satisfied ☐ Good	
Date & Time Finished		□ 3. Moderately Satisfied □ 4. Very Satisfied □ 5. Excellent □ 5. Extremely Satisfied	
		Comments & Suggestion	n
Checked :	PPO Head/Director (Name and Signature)	Name &Signature	
Notes:		Designation/Position	