



OFFICE OF THE DIRECTOR FOR PHYSICAL PLANT

Visca, Baybay City, Leyte, PHILIPPINES Telefax: 1041(LOCAL) Email: www.ppo.@vsu.edu.ph Website: www.vsu.edu.ph

REPAIR AND MAINTENANCE REQUEST

Filled in by requesting party	Filled in by PPC	
	0, 2022 Date received	:
House No!	# 46 Received by	Name & Signature
• • • • • • • • • • • • • • • • • • • •	Campus Designation/	:
	N F. JANSALIN Signature Control number	:
Please check and specify the nature of work re	equested	
✓ Vehicle Repair✓ Welding Works✓ Machining works (lathe, shaper, drill press, etc.)	 □ Carpentry & Furniture Works □ Plumbing Works □ Instrumentation equipment & Laboratory instrument 	 ☐ Electrical Works ☐ Heating, Ventilating, Air conditioning & Refrigeration ☐ Others (specify):
water later outperfeet arts.	☐ Available	□ Not Available
Bri	ief Description of Repair and Maintena	
Bri Check up and repair of electrical connect	ief Description of Repair and Maintena tion in Apartment # 46	nce
Bri Check up and repair of electrical connect	ief Description of Repair and Maintena	
Bri Check up and repair of electrical connect	ief Description of Repair and Maintenantion in Apartment # 46 Manpower Requirement	nce
Bri Check up and repair of electrical connect	ief Description of Repair and Maintenantion in Apartment # 46 Manpower Requirement	Estimated hours/days to finished
Bri Check up and repair of electrical connect	ief Description of Repair and Maintenantion in Apartment # 46 Manpower Requirement Filled in by the requesting party after	Estimated hours/days to finished
Bri Check up and repair of electrical connect	ief Description of Repair and Maintenantion in Apartment # 46 Manpower Requirement Filled in by the requesting party after Service Satisfaction	Estimated hours/days to finished er the conduct of repair and maintenance OVER-ALL RATING
Bri Check up and repair of electrical connect	ief Description of Repair and Maintenantion in Apartment # 46 Manpower Requirement Filled in by the requesting party after Service Satisfaction 1. Not Satisfied	Estimated hours/days to finished or the conduct of repair and maintenance OVER-ALL RATING 1 Poor 2 Fair

Vision: Mission: