



OFFICE OF THE DIRECTOR FOR PHYSICAL PLANT

Visca, Baybay City, Leyte, PHILIPPINES Telefax: 1041(LOCAL)

Email: www.ppo.@vsu.edu.ph Website: www.vsu.edu.ph

REPAIR AND MAINTENANCE REQUEST

Filled in by requesting party			Filled in by PPC)	
Date filed Building/Facility/ House No/ Apartment No./ Department		April 2022	Date received Received by	:Name	e & Signature
Location	:		Designation/ Position	:	o d Oighataro
Requesting part Designation/ Position	Nam	e & Signature ead, DMet	Maintenance control number	:	
1 OSITION					
Please check and	specify the nature of we	ork requested			
☐ Vehicle Rep☐ Welding Wo☐ Machining w(lathe, shape	orks	☐ Plumbing Wo	on equipment	Heating, Ventilating, Air conditioning & Refrigeration equipment Others (specify):	
Materials/Supp	lies/Parts:	☐ Available		Not Availab	le
Electrical Works: there is short circuit; only temporary electrical line & limited sockets for the lamp; the generator set for standby power needs check-up for repair so that it can be used Water Supply: Water supply is only outside of the building, water should also be distributed inside the building especially the comfort room & the kitchen area Carpentry & Furniture works: the office, quarter & kitchen need repair Note: The Agromet Station is used as laboratory facilities of the BS Meteorology students of VSU.					
Filled in by PPO) personnel				
Part/Supplies/Materials Required		Manpower R	Requirement	Estimated hours/days to finished	
		Filled in by	the requesting party after	er the conduct of repair	and maintenance
Conducted — by:	PPO Personn	Ci	ice Satisfaction	OVER-ALL RATING	
(Name & Signa		ure)	Not Satisfied	☐ 1 Poor	☐ 2 Fair
PPO Unit			Slightly Satisfied Moderately Satisfied	☐ 3 Good ☐ 5 Excellent	☐ 4 Very Good
	Engr. MARIO LILIO I	•	Very Satisfied		s & Suggestion
Verified by:	VALENZONA PPO Head (Name & Signat	□ 5. E	Extremely Satisfied		
		Nam	e and Signature		