



OFFICE OF THE DIRECTOR FOR PHYSICAL PLANT

Visca, Baybay City, Leyte, PHILIPPINES Telefax: 1041 (LOCAL) Email: www.ppo.@vsu.edu.ph Website: www.vsu.edu.ph

REPAIR AND MAINTENANCE REQUEST

Filled in by req	luesting party			Filled in by PPC		
Date filed		ıly 12, 2022		Date received	1:	
Building/Facilit House No/ Apartment No. Department	Departme	ent of Soil So 07- Pedology	ogy lab		Nam	e & Signature
Location	equesting party : SHEILA MARKO Name & Sign esignation/		mpus Designation/			
Requesting pa Designation/ Position				Maintenance control number	:	
Please check an	nd specify the nature of w	ork requested				
□ Vehicle Repair□ Welding Works□ Machining works		□ Plu	Carpentry & Furniture Works Plumbing Works Instrumentation equipment & Laboratory instrument		☐ Electrical Works ☐ Heating, Ventilating, Air conditioning & Refrigeration ☐ Others (specify):	
(lathe, sha		□ Av	ailable		☐ Not Availab	ile
(lathe, sha		Brief Descr		ir and Maintena		ole
(lathe, sha Materials/Sup 1. To fix	Poplies/Parts: Hot plate and Fumeh	Brief Descr	iption of Repai			ole
(lathe, sha) Materials/Sup 1. To fix Filled in by PP	pplies/Parts:	Brief Descr			nce	urs/days to finished
(lathe, shaped) Materials/Sup 1. To fix Filled in by PP Part/Supplies. onducted y:	Poplies/Parts: Hot plate and Fumeh	Brief Descr	anpower Requi	rement equesting party after atisfaction catisfied	Estimated ho	urs/days to finished r and maintenance ALL RATING □ 2 Fair
(lathe, sha) Materials/Sup 1. To fix Filled in by PP	Hot plate and Fumeh O personnel //Materials Required	Brief Descr	anpower Requi	rement equesting party afte atisfaction	Estimated ho over the conduct of repair OVER-A 1 Poor 3 Good 5 Excellent	urs/days to finished r and maintenance

Vision:

A globally competitive university for science, technology, and environmental

Mission:

No.

Development of a highly competitive human resource, cutting-edge scientific knowledge and innovative technologies for sustainable communities and environment.