

OFFICE OF THE DIRECTOR FOR PHYSICAL PLANT

Visca, Baybay City, Leyte, PHILIPPINES Telefax: 1041(LOCAL) Email: www.ppo.@vsu.edu.ph Website: www.vsu.edu.ph

REPAIR AND MAINTENANCE REQUEST

Filled in by requesting party		Filled in by PPC	
Building/Facility/ House No/	: 10, 2021	Date received	
Apartment No./ Department Location : Cash Di	vision Admin	Received by Designation/	Name & Signature
Location Cash Di	vision, Admin.	Position	:
requesting party	ever Atupan	Maintenance control number	:
FUSILIUII	Cash Division		
Note: i. Three (3) copies: (1) fo ii. One (1) job request in a iii. Job request control nur		PPO unit Head & (1) for maintenance team
Please check and specify the nature o	f work requested		
☐ Vehicle Repair	☐ Carpentry Works	& Furniture	☐ Electrical Works
☐ Welding Works	☐ Plumbing	Works	Heating, Ventilating, Air conditioning & Refrigeration
☐ Machining works (lathe, shaper, drill press, etc.	Instrument equipment		Others (specify):
(,,	2 & Laborato	ory instrument	Air
			Conditioning
Brief I	Description of Repa	air and Maintei	nance
Brief I Materials/Supplies/Parts:	Description of Repa	air and Maintei	nance ☐ Not Available
2		air and Maintei	
Materials/Supplies/Parts:			
Materials/Supplies/Parts: Filled in by PPO personnel Part/Supplies/Materials	☐ Available		□ Not Available Estimated hours/days to
Materials/Supplies/Parts: Filled in by PPO personnel Part/Supplies/Materials Required	☐ Available Manpower Re		□ Not Available Estimated hours/days to finished
Materials/Supplies/Parts: Filled in by PPO personnel Part/Supplies/Materials	☐ Available		□ Not Available Estimated hours/days to

Vision: Mission: A globally competitive university for science, technology, and environmental conservation. Development of a highly competitive human resource, cutting-edge scientific knowledge and innovative technologies for sustainable communities and environment.

Page 1 of 1 FM-PPO-09 v2 01-15-2021