



OFFICE OF THE DIRECTOR FOR PHYSICAL PLANT

Visca, Baybay City, Leyte, PHILIPPINES Telefax: 1041(LOCAL) Email: www.ppo.@vsu.edu.ph Website: www.vsu.edu.ph

REPAIR AND MAINTENANCE REQUEST

Filled in by requesting party			Filled in by PPC		
Date filed Building/Facility House No/ Apartment No./		uary 8, 2023	Date received Received by	:	
Department Location Requesting par Designation/ Position	ty : <u>JEROME</u>	RMI Building O. ARRIBADO & Signature Director	Designation/ Position Maintenance control number	Nar : :	me & Signature
Please check and	d specify the nature of wo	ork requested			
☐ Welding Works ☐ Plumbing Wo			ion equipment	 ☐ Electrical Works ☑ Heating, Ventilating, Air conditioning & Refrigeration ☐ Others (specify): 	
Materials/Supplies/Parts: Available Not Available					
		Brief Description of I	Repair and Maintena	nce	
Repair and maintenance of the air conditioning unit(s) in the Eco-FARMI.					
Filled in by PPO	O personnel				
Part/Supplies/Materials Required		Manpower F	Manpower Requirement		nours/days to finished
Filled in by		the requesting party after the conduct of repair and maintenance			
Conducted -	PPO Personn	el Sen	rice Satisfaction	OVER-ALL RATING	
by:	(Name & Signat	ure)	Not Satisfied	☐ 1 Poor	☐ 2 Fair
PPO Unit		_ 2	Slightly Satisfied	□ 3 Good	☐ 4 Very Good
Checked & Verified by:			Moderately Satisfied	5 Excellent	-
	PPO Head		Very Satisfied	Comments & Suggestion	
	(Name & Signat	_	Extremely Satisfied	Comme	nta di daggestion
		Nan	ne and Signature		

Vision: Mission: A globally competitive university for science, technology, and environmental conservation. Development of a highly competitive human resource, cutting-edge scientific knowledge and innovative technologies for sustainable communities and environment.