

OFFICE OF THE DIRECTOR FOR **QUALITY ASSURANCE**

Visca, Baybay City, Leyte, PHILIPPINES Telefax: +63 53 563 7534; Local 1076

Email: qac@vsu.edu.ph Website: www.vsu.edu.ph

GENERAL OBSERVATIONS AND OPPORTUNITIES FOR IMPROVEMENT LIST

Audit No.: 03

Audit

October 12, 2021

Audited

Office of the Head of Motor Pool

Control No.	General Observations and Opportunities for Improvement	PLANNED ACTIONS			
		Action Items	Target Date	Responsible	Status
MPSO-OFI- 21-01	Ensure that copies of the required Quality Procedures are available on file.	1 Request copy of the updated QP to ODQA. 2. Re-orient MPSO personnel for university QMS and PPO QP & GL.	January 2022 2ND WEEK	MG BUrlas and dDRC	
MPSO-OFI- 21-02	Ensure to clearly identify or quantity deliverable of the unit to the OTP.	1. REVIEW THE PPO OTP SINCE IT IS CONSOLIDATED AS ONE	SND MEEK SOSS JUNITARY	ME BARTAL	
MPSO-OFI- 21-03	all of the vehicles belonging to units outside of MPSO. Motor vehicles and other equipment are serviced according to the maintenance plan. However, all vehicles	1. UPDATE EXISTING VEHICLE MAINTENANCE 2. SUBMIT PROPOSAL FOR A CENTRALIZED DISPATCHING FOR ALL UNIVERSITY VEHICLE SINCE MOST OF THE REPAIR VERE CONDUCTED BY THE OFFICE	FEBRUARY 2022 1ST WEEK	MG BURLAS AND MAS MECHANICS	