



OFFICE OF THE DIRECTOR FOR **PHYSICAL PLANT**

Visca, Baybay City, Leyte, PHILIPPINES Telefax: 1041(LOCAL)

Email: www.ppo.@vsu.edu.ph Website: www.vsu.edu.ph

REPAIR AND MAINTENANCE REQUEST

Filled in by requesting party		Filled in by PPC		
	ember 5, 2022	Date received	:	
	ed Research and vation Center	Received by	Name & Signature	
Location : Visayas State University		Designation/ Position	:	
Nan Designation/	RESA F. LORETO ne & Signature	Maintenance control number	:	
Position Di	ector, ARIC			
Please check and specify the nature of work requested				
☐ Vehicle Repair ☐ Welding Works	elding Works		s Heating, Ventilating, Air conditioning & Refrigeration	
☐ Machining works ☐ Instrumentation equipment (lathe, shaper, drill press, etc.) ☐ Laboratory instrument			Others (specify):	
Materials/Supplies/Parts: Available Not Available				
Brief Description of Repair and Maintenance				
Check and repair of electrical connection/outlet in Tuklas Lunas Development Center laboratory.				
Filled in by PPO personnel				
Part/Supplies/Materials Required Manpower Requirement		equirement	Estimated hours/days to finished	
	Filled in by t	he requesting party after	er the conduct of repair and maintenance	
Servi		ce Satisfaction	OVER-ALL RATING	
	☐ 1. N	ot Satisfied	☐ 1 Poor ☐ 2 Fair	
	2.		☐ 3 Good ☐ 4 Very Good	
	□ 3. □ 4.	Satisfied	5 Excellent	
		Very Satisfied Extremely	Comments & Suggestion	
S		atisfied		

Vision:

A globally competitive university for science, technology, and environmental

Mission:

Development of a highly competitive human resource, cutting-edge scientific knowledge and innovative technologies for sustainable communities and environment.

Page 1 of 2 FM-PPO-09 v0 02-28-2022