



OFFICE OF THE DIRECTOR FOR PHYSICAL PLANT

Visca, Baybay City, Leyte, PHILIPPINES Telefax: 1041(LOCAL) Email: www.ppo.@vsu.edu.ph Website: www.vsu.edu.ph

REPAIR AND MAINTENANCE REQUEST

Filled in by reg	lesting narty			Filled in by PPC)			
Filled in by requesting party Date filed : January 9, 2023				Date received				
Building/Facility House No/ Apartment No./ Department		dai y 9, 2023		Received by		Name	& Signature	
Location	: Eco-FARM Build			Designation/ Position	: .			
Requesting particles Designation/Position	Nam	ER C. LUSAN e & Signature C-Director	TA	Maintenance control number	:			
Please check and	d specify the nature of w	ork requested						
☐ Welding Works ☐ F ☐ Machining works ☐ II			Carpentry & Furniture Works Plumbing Works Instrumentation equipment & Laboratory instrument			Electrical Works Heating, Ventilating, Air conditioning & Refrigeration Others (specify):		
Materials/Sup	plies/Parts:	☐ Availa	ble			Not Available	е	
		Brief Descrip	tion o	of Repair and Maintena	nce			
Repair and r	maintenance of the	e air conditio	ning	units in the Eco-FAF	RMI.			
Filled in by PP								
Part/Supplies	Materials Required	Mai	npowe	r Requirement		Estimated hou	rs/days to finished	
	by the requesting party after	er the	conduct of repair	and maintenance				
Conducted PPO Personn				ervice Satisfaction	OVER-ALL RATING			
by:	(Name & Signature)] 1.	Not Satisfied	1	I Poor	☐ 2 Fair	
PPO Unit			2.	Slightly Satisfied	□3	3 Good	4 Very Good	
Checked &			3.	Moderately Satisfied	□ 5	5 Excellent		
Verified by:	PPO Head (Name & Signature)] 4.	Very Satisfied		Comments & Suggestion		
			5.	Extremely Satisfied				
			N	ame and Signature				

No.