

OFFICE OF THE DIRECTOR FOR PHYSICAL PLANT

Visca, Baybay City, Leyte, PHILIPPINES Telefax: 1041(LOCAL) Email: www.ppo.@vsu.edu.ph Website: www.vsu.edu.ph

REPAIR AND MAINTENANCE REQUEST

Filled in by requesting party	Filled in b	DY PPO
Date filed : Teg, 141 Building/Facility/ House No/ Apartment No./ Department : Biotech Requesting party : The Standard Consition : Asst. Provided the Standard Consistency : Asst. Prov	Date received in R	Name & Signature In large state of the stat
iii. Job request control nui		
Please check and specify the nature of	of work requested	
☐ Vehicle Repair	Carpentry & Furnitu	re Electrical Works
☐ Welding Works	Works ☐ Plumbing Works	☐ Heating, Ventilating, Air
☐ Machining works (lathe, shaper, drill press, etc.)	☐ Instrumentation	conditioning & Refrigeratio Others (specify):
Brief	Description of Repair and M	
	Description of Repair and M	aintenance
Door is ready to be	Description of Repair and M	aintenance
Door is ready to be Materials/Supplies/Parts:	Description of Repair and Mingl replacing the do installed.	aintenance or Claitchen and bothro
Door is ready to be Materials/Supplies/Parts:	Description of Repair and Mingl replacing the do installed.	aintenance Or Claitchen and bothno
To continue change Door is ready to be Materials/Supplies/Parts: Filled in by PPO personnel Part/Supplies/Materials	Description of Repair and Minghaphoing the do installed. Available	aintenance or Claitchen and bothro Not Available Estimated hours/days to

Vision: Mission: A globally competitive university for science, technology, and environmental conservation. Development of a highly competitive human resource, cutting-edge scientific knowledge and innovative technologies for sustainable communities and environment.

Page 1 of 1 FM-PPO-09 v2 01-15-2021

No.