



OFFICE OF THE DIRECTOR FOR PHYSICAL PLANT

Visca, Baybay City, Leyte, PHILIPPINES Telefax: 1041(LOCAL) Email: www.ppo.@vsu.edu.ph Website: www.vsu.edu.ph

REPAIR AND MAINTENANCE REQUEST

Filled in by requesting party	Filled in by PP0)
Date filed : 3-9- Building/Facility/ House No/ Apartment No./ Department Location : CMTOTTE Requesting party Designation/ Position : 14eol, D	Designation/ Position Maintenance control number	Name & Signature
Note:	requesting party, (1) for PPO unit Head very of PPO unit	& (1) for maintenance team
Please check and specify the nature of w	ork requested	
☐ Vehicle Repair	☐ Carpentry & Furniture Works	☐ Electrical Works
☐ Welding Works	☐ Plumbing Works	 Heating, Ventilating, Air conditioning & Refrigeration
☐ Machining works	☐ Instrumentation	Others (specify):
(lathe, shaper, drill press, etc.)	equipment & Laboratory instrument	Roof works
Brief De	scription of Repair and Mainte	enance
Repair of leaking	f	
Materials/Supplies/Parts:	Available	☐ Not Available
Filled in by PPO personnel		
Part/Supplies/Materials Required	Manpower Requirement	Estimated hours/days to finished
Inspected by:	Checked & Verified	Approved by:
PPO Maintenance	by: PPO Unit Head	PPO Director