



OFFICE OF THE DIRECTOR FOR PHYSICAL PLANT

Visca, Baybay City, Leyte, PHILIPPINES Telefax: 1041(LOCAL) Email: www.ppo.@vsu.edu.ph Website: www.vsu.edu.ph

REPAIR AND MAINTENANCE REQUEST

Filled in by requesting party			Filled in by PP)	
Date filed : Building/Facility/ House No/	May 16, 2022		Date received	:	
Apartment No./	ISR	DS	Received by	No	
Department Location :	VSU, Visca,	Baybay City	Designation/	Nar :	me & Signature
Requesting party : MIZAEL B. CERNA			Maintenance	*	
Requesting party :	NA Signature	control number			
Designation/ Position : Admin. Aide 3					
Please check and specify the nature of work requested					
☐ Vehicle Repair	☐ Carpentry &	Furniture Works	☐ Electrical W		
☐ Welding Works ☐ Plumbing W			orks	Heating, Ver	ntilating, Air & Refrigeration
☐ Machining works		on equipment	Others (spec		
(lathe, shaper, drill press, etc.) & Laboratory instrument					
Materials/Supplies/Parts: Available Not Available					
Brief Description of Repair and Maintenance					
Check aircon wiring at CRGalgo's room.					
Filled in by PPO personnel			可能是在1000年的中央中央的1000年的		
Part/Supplies/Materials Required		Manpower R	Requirement	Estimated hours/days to finished	
Filled in by the requesting party after the conduct of repair and maintenance					
Conducted PPO Person			ice Satisfaction		
(Λ	lame & Signature)	□ 1. N	Not Satisfied	☐ 1 Poor	☐ 2 Fair
PPO Unit			Slightly Satisfied	□ 3 Good	☐ 4 Very Good
		3 N	Moderately Satisfied	5 Excellent	Li 4 Very Good
Checked & Verified by: PPO Head			/ery Satisfied		ts & Suggestion
(N	lame & Signature)		Extremely Satisfied		
		Name	e and Signature		

Vision: Mission: