



OFFICE OF THE DIRECTOR FOR PHYSICAL PLANT

Visca, Baybay City, Leyte, PHILIPPINES Telefax: 1041(LOCAL)

Email: www.ppo.@vsu.edu.ph Website: www.vsu.edu.ph

REPAIR AND MAINTENANCE REQUEST

Filled in by requesting party			Filled in by PPC)		
Date filed Cotober 03, 2022			Date received	:		
Building/Facility/ House No/ Apartment No./ Department	73 60011000000	Staff Male Comfort Room ent of Agronomy	Received by	Name	& Signature	
Location :	VSU, Upper Campus		Designation/ Position	:		
Requesting party :		O. Escasinas e & Signature	Maintenance control number			
Designation/ Position :		artment Head				
Please check and specif	fy the nature of w	ork requested				
□ Vehicle Repair □ Carpentry & □ Welding Works □ Plumbing W			tion equipment	☐ Electrical Works ☐ Heating, Ventilating, Air conditioning & Refrigeration ☐ Others (specify):		
Materials/Supplies/F	Parts:	☐ Available		☐ Not Available	e	
		Brief Description of	Repair and Maintena	nce .		
1. To	repair leaking to	oilet bowl and urinal pip	e			
Filled in by PPO pers	onnel					
Part/Supplies/Materials Required		Manpower	Requirement	Estimated hours/days to finished		
Fill			y the requesting party after	er the conduct of repair	and maintenance	
Conducted by: PPO Personnel (Name & Signature) PPO Unit		01	Service Satisfaction		OVER-ALL RATING	
		fure) 1.	Not Satisfied	☐ 1 Poor	☐ 2 Fair	
		2.	Slightly Satisfied	□ 3 Good	☐ 4 Very Good	
Charled 9			Moderately Satisfied	☐ 5 Excellent		
Checked & Verified by:	PPO Head		Very Satisfied	Comments & Suggestion		
~	(Name & Signat		Extremely Satisfied			
		Nar	ne and Signature			

Vision:

Mission:

A globally competitive university for science, technology, and environmental

conservation.

Development of a highly competitive human resource, cutting-edge scientific knowledge and innovative technologies for sustainable communities and environment.

Page 1 of 1 FM-PPO-09 v0 02-28-2022