



OFFICE OF THE DIRECTOR FOR PHYSICAL PLANT

Visca, Baybay City, Leyte, PHILIPPINES Telefax: 1041(LOCAL) Email: www.ppo.@vsu.edu.ph Website: <u>www.vsu.edu.ph</u>

REPAIR AND MAINTENANCE REQUEST

Filled in by requesting party				Filled in by PPO			
Date filed Building/Facility House No/	y/	May 2022		Date received Received by	:		
Apartment No./ Department Location	· -			Designation/	Na	ame & Signature	
Requesting particles Designation/Position	Nam	LIE S. ANDAN e & Signature ead, DMet		Position Maintenance control number	:		
- · · ·							
Please check an	d specify the nature of w	ork requested					
 □ Vehicle Repair □ Welding Works □ Machining works □ Instrumentation (lathe, shaper, drill press, etc.) 				quipment	conditionin Others (sp	entilating, Air g & Refrigeration	
Materials/Supplies/Parts: only the aircon unit					Not Available		
Brief Description of Repair and Maintenance							
Conditioning: Meteorology	Installation of Airco	n Unit at the Meteore	ology of	ffice and CLAWS	S laboratory of t	the Department of	
Filled in by PP	O personnel						
		Manpowe	Manpower Requirement		Estimated hours/days to finished		
		Filled in	by the re	the requesting party after the conduct of repair and maintenance			
Conducted – by:	PPO Personr	101	Service Satisfaction		OVER-ALL RATING		
(Name & Signat							
DDO Unit	(Name & Signa		Not S	atisfied	☐ 1 Poor	☐ 2 Fair	
PPO Unit	(Name & Signa	1		atisfied ly Satisfied	☐ 1 Poor ☐ 3 Good	⊔ 2 Fair □ 4 Very Good	
-			Slight			☐ 4 Very Good	
PPO Unit - Checked & Verified by:	Engr. MARIO LILIO VALENZONA	1.	Slight Mode Very S	ly Satisfied rately Satisfied Satisfied	☐ 3 Good	☐ 4 Very Good	
Checked &	Engr. MARIO LILIO	P.	Slight Mode Very S	ly Satisfied rately Satisfied	☐ 3 Good	☐ 4 Very Good	
- Checked &	Engr. MARIO LILIO VALENZONA PPO Head	P 1 3 4 5	Slight Mode Very S Extrer	ly Satisfied rately Satisfied Satisfied	☐ 3 Good	☐ 4 Very Good	