



PHYSICAL PLANT OFFICE

Visca, Baybay City, Leyte, PHILIPPINES Telefax: 1041(LOCAL) Email: www.ppo.@vsu.edu.ph

Website: www.vsu.edu.ph

REPAIR AND MAINTENANCE REQUEST

REQUEST INFORMATION	
Filled in by requesting party	Filled in by PPO
Date filed : 25 July 2024	Date received :
Building/Department : ISRDS	Received by
Location : ISRDS BIDANI Room	Name & Signature Designation/Position :
Requesting party SALOMA B. GISULGA	Request Reference :
Name & Signature Designation/Position : S R S	VINUINDE
Contact no./Email :	
Please check and specify the nature of work requested:	
☐ Vehicle Repair ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐	urniture Works
☐ Welding Works ☐ Plumbing W	/orks Heating, Ventilating, Air conditioning & Refrigeration
☐ Machining works (Lathe, shaper, drill press, etc.) ☐ Instrumentation equipment & Laboratory instrument ☐ Others (specify in the brief description below)	
Brief Description of the Nature of Work Requested	
Check and renair aircon unit at the BIDANI Room	
INSPECTION (Filled in by PPO Personnel)	
Date of Inspection: Time started: [AM] [PM] Time ended: [AM] [PM]	
	☐ For Outsourcing Repair and Maintenance Estimated hours/days
Materials/Parts Manpower Required:	of repair:
☐ Available ☐ Available ☐ Not Available ☐ Not Available	Schedule of repair:
Conducted: Confirmed:	
PPO Maintenance Personnel/Name & Sign	Name and Signature
Designation/Position	Designation/Position
ACCOMPLISHMENT	
Filled in by PPO Personnel	Filled in by Requesting Party
Conducted : PPO Maintenance Personnel	Service Satisfaction OVER ALL RATING
(Name and Signature)	☐ 1. Not Satisfied ☐ 1. Poor ☐ 2. Fair ☐ 2. Slightly Satisfied ☐ 3. Good ☐ 4. Very
Date & Time Started	☐ 2. Slightly Satisfied ☐ 3. Good ☐ 4. Very ☐ 3. Moderately Satisfied ☐ Good
Date & Time	☐ 4. Very Satisfied ☐ 5. Excellent
Finished	□ 5. Extremely Satisfied Comments & Suggestion
Checked	2
&verified : PPO Head/Director (Name and Signature)	Name &Signature
Notes:	Designation/Position
	Dodgiation odition

Vision: Mission: