



REPAIR AND MAINTENANCE REQUEST

REQUEST INFORMATION

Filled in by requesting party

Date filed : August 29, 2024

Building/Department : ISRDS

Location : ISRDS

Requesting party : LILIAN B. NUÑEZ
Name & Signature

Designation/Position : Director

Contact no./Email :

Filled in by PPO

Date received :

Received by

Name & Signature

Designation/Position :

Request Reference
Number

Please check and specify the nature of work requested:

☐ Vehicle Repair

☐ Carpentry & Furniture Works

☐ Electrical Works

☐ Welding Works

☐ Plumbing Works

☐ Heating, Ventilating, Air
conditioning & Refrigeration

☐ Machining works
(Lathe, shaper, drill press, etc.)

☐ Instrumentation equipment
& Laboratory instrument

☐ Others (specify in the brief description
below)

Brief Description of the Nature of Work Requested

Repair the entrance gutter of the ISRDS building and the administrative office side gutter then clean and remove leaves that obstruct the flow.

INSPECTION (Filled in by PPO Personnel)

Date of Inspection: _____ Time started: _____ [AM] [PM] Time ended: _____ [AM] [PM]

☐ In-House Repair and Maintenance

☐ For Outsourcing Repair and Maintenance

Materials/Parts

Manpower Required: _____

Estimated hours/days
of repair: _____

☐ Available

☐ Available

Schedule of repair: _____

☐ Not Available

☐ Not Available

Conducted:

PPO Maintenance Personnel/Name & Sign

Confirmed:

Name and Signature

Designation/Position

Designation/Position

ACCOMPLISHMENT

Filled in by PPO Personnel

Conducted by : PPO Maintenance Personnel
(Name and Signature)

Date & Time
Started :

Date & Time
Finished :

Checked & verified : PPO Head/Director
(Name and Signature)

Notes:

Filled in by Requesting Party

Service Satisfaction

OVER ALL RATING

- ☐ 1. Not Satisfied
☐ 2. Slightly Satisfied
☐ 3. Moderately Satisfied
☐ 4. Very Satisfied
☐ 5. Extremely Satisfied

- ☐ 1. Poor ☐ 2. Fair
☐ 3. Good ☐ 4. Very Good
☐ 5. Excellent

Comments & Suggestion

Name & Signature

Designation/Position