

OFFICE OF THE DIRECTOR FOR PHYSICAL PLANT

Visca, Baybay City, Leyte, PHILIPPINES Telefax: 1041(LOCAL) Email: www.ppo.@vsu.edu.ph Website: www.vsu.edu.ph

REPAIR AND MAINTENANCE REQUEST

Filled in by requesting party		Filled in by PPC	
Date filed : January 12,	2022	Date received	:
Building/Facility/ House No/ Apartment No./ Department Office of He Records & A (OHRA)		Received by	Name & Signature
Location : G/F Admin.	Building	Designation/	1
Requesting party: MARIA ROBERT Designation/ Position : Head, OHR/	A S. MIRAFLOR	Position Maintenance control number	:
ii. One (1) job request in ev iii. Job request control numb	ery of PPO unit. per is required.	for PPO unit Head &	(1) for maintenance team
Please check and specify the nature of	work requested		
 □ Vehicle Repair □ Welding Works □ Machining works □ Instrumentation equipment & Laboratory instrument 		 □ Electrical Works □ Heating, Ventilating, Air conditioning & Refrigeration □ Others (specify): 	
Brief Description of Repair and Maintenance To repair dilapidated steel cabinets.			
Materials/Supplies/Parts:	☐ Availab	le	Not Available
Filled in by PPO personnel			
Part/Supplies/Materials Required	Manpowe	r Requirement	Estimated hours/days to finished
Inspected by:	Checked & Verified by:		Approved by:
PPO Maintenance	~y.	PPO Unit Head	PPO Director