

OFFICE OF THE DIRECTOR FOR PHYSICAL PLANT

Visca, Baybay City, Leyte, PHILIPPINES Telefax: 1041(LOCAL) Email: www.ppo.@vsu.edu.ph Website: www.vsu.edu.ph

REPAIR AND MAINTENANCE REQUEST

Filled in by requesting party		Filled in by PPO		
Date filed : 1/2	1/2022	Date received	1	
Building/Facility/ House No/ Apartment No./ Department	DFS	Received by		Name & Signature
Location : CFES Build	ing to Nursery	Designation/ Position	:	
Requesting party	N. POLINAR	Maintenance control number	:	
Designation/ : Hea	d, DFS			
Note: i. Three (3) copies: (1) for ii. One (1) job request in et iii. Job request control num	very of PPO unit) for PPO unit Head &	(1) for main	ntenance team
Please check and specify the nature of w	ork requested			
☐ Vehicle Repair	☐ Carpentry & Furniture Works		☑ Elect	rical Works
☐ Welding Works	☐ Plumbing Works			ng, Ventilating, Air tioning & Refrigeration
Machining works equipment		nentation tratory instrument		rs (specify):
Brief Description of Repair and Maintenance				
Installing of service wire				
Materials/Supplies/Parts:	☐ Available	е		Not Available
Filled in by PPO personnel				
Part/Supplies/Materials				
Required	Manpower	Requirement	Estim	ated hours/days to finished
	Manpower	Requirement	Estim	7
	Manpower	Requirement	Estim	7
	Checked & Verified by:	Requirement PPO Unit Head	Approv	finished