

OFFICE OF THE DIRECTOR FOR PHYSICAL PLANT

Visca, Baybay City, Leyte, PHILIPPINES Teiefax: 1041(LOCAL) Email: www.ppo.@vsu.edu.ph Website: www.vsu.edu.ph

REPAIR AND MAINTENANCE REQUEST

Filled in by requesting party		Filled in by PPC	
Date filed : Fe Building/Facility/	bruary 03, 2021	Date received	
TOUSE INCO	Forest Science	Received by	Name & Signature
ocation : Co	llege of Forestry	Designation/ Position	1
Pequeeting party : Re	emy R. Lebante	Maintenance	*
Designation/	Lab. Tech.		
III. Job request conti	(1) for requesting party, (1) est in every of PPO unit rol number is required.) for PPO unit Head &	(1) for maintenance team
lease check and specify the natu			
☐ Vehicle Repair	Works	ntry & Furniture	☐ Electrical Works
☐ Welding Works		ng Works	Heating, Ventilating, Air conditioning & Refrigeration
☐ Machining works ☐ Instrume equipment		nentation	Others (specify):
Di	ef Description of Re	pair and mainter	Tance
Concrete ceiling leakage nee	ed to be repair		
Materials/Supplies/Parts:	CONTRACTOR OF THE PARTY OF THE		
	☐ Available	8	☐ Not Available
Filled in by PPO personnel		,	☐ Not Available
Part/Supplies/Materials Required	☐ Available	Requirement	Not Available Estimated hours/days to finished
Part/Supplies/Materials	☐ Available		Estimated hours/days to
Part/Supplies/Materials	☐ Available		Estimated hours/days to
Required	Manpower F		Estimated hours/days to finished Approved
Part/Supplies/Materials	Checked & Verified by:		Estimated hours/days to finished