

OFFICE OF THE DIRECTOR FOR PHYSICAL PLANT

Visca, Baybay City, Leyte, PHILIPPINES Telefax: 1041(LOCAL) Email: www.ppo.@vsu.edu.ph Website: www.vsu.edu.ph

REPAIR AND MAINTENANCE REQUEST

Filled in by requesting party		Filled in by PPO			
	ber 15, 2022	Date received	:		
	rissue Culture new bldg)	Received by	Name	& Signature	
Location ;		Designation/ Position	:		
Requesting party : _FLORA N	MIA Y. DUATIN	Maintenance control number	1		
FOSITION	ect Leader				
Note: i. Three (3) copies: (1) for requesting party, (1) for PPOunit Head & (1) for maintenance team ii. One (1) job request in every of PPO unit iii. Job request control number is required.					
Please check and specify the nature of	f work requested				
☐ Vehicle Repair	☐ Carpentry Works		☐ Electrical Works ☐Heating, Ventilating, Air		
☐ Welding Works				g & Refrigeration	
☐ Machining works		☐ Instrumentation equipment		Others (specify):	
		tory instrument			
Brief Description of Repair and Maintenance					
DIO.	occompaint of the	copun una mante	nance		
To check possible location of outlets for culture cabinets at New Tissue Culture Building.					
Materials/Supplies/Parts:		le	☐ Not Available		
Filled in by PPOpersonnel					
Part/Supplies/Materials Required	Manpowe	r Requirement		nours/days to shed	
Inspected by: PPO Maintenance	Checked & Verified — by: —		Approved by:		
PPO Maintenance	-1.	PPO Unit Head		PPO Director	