

## OFFICE OF THE DIRECTOR FOR PHYSICAL PLANT

Visca, Baybay City, Leyte, PHILIPPINES Telefax: 1041(LOCAL) Email: www.ppo.@vsu.edu.ph Website: www.vsu.edu.ph

## REPAIR AND MAINTENANCE REQUEST

Filled in by requesting party		Filled in by PPO		
Date filed : 6 December	2021	Date received	:	
Building/Facility/ House No/ Apartment No./ Department  Office of He Records & A (OHRA)	Archives	Received by	-	Name & Signature
Location : G/F Admin.	Building	Designation/ Position	:	
Requesting party: MARIA ROBERT	A S. MIRAFLOR	Maintenance control number	:	
Designation/ : Head, OHRA				
Position . Iteau, Office				
i. Three (3) copies: (1) for requesting party, (1) for PPO unit Head & (1) for maintenance team ii. One (1) job request in every of PPO unit iii. Job request control number is required.				
Please check and specify the nature of v	ork requested			
☐ Vehicle Repair	☐ Carper Works	ntry & Furniture		Electrical Works
☐ Welding Works		ing Works		Heating, Ventilating, Air
		nentation		conditioning & Refrigeration
☐ Machining works (lathe, shaper, drill press, etc.)	equipm	nent oratory instrument		Others (specify):
Brief Description of Repair and Maintenance				
To install 1 additional electrical outlet.				
Materials/Supplies/Parts:	☐ Available	)		Not Available
Filled in by PPO personnel				
Part/Supplies/Materials Required	Manpower	Requirement		Estimated hours/days to finished
Inspected by:  PPO Maintenance	Checked & Verified by:	-	Ap by:	proved: PPO Director
		PPO Unit Head		PPU Director