



REPAIR AND MAINTENANCE REQUEST

Filled in by requesting party	
Date filed	: January 4, 2022
Building/Facility/ House No/ Apartment No./ Department	: Department of Physics
Location	: 1/F Old Library Building VSU, Visca, Baybay City, Leyte
Requesting party	: <u>REV RHIZZA L. AURE</u>
Designation/ Position	: Head, DPhys

Filled in by PPO	
Date received	:
Received by	: _____ Name & Signature
Designation/ Position	:
Maintenance control number	:

Note:

- Three (3) copies: (1) for requesting party, (1) for PPO unit Head & (1) for maintenance team
- One (1) job request in every of PPO unit
- Job request control number is required.

Please check and specify the nature of work requested

- | | | |
|--|---|---|
| <input type="checkbox"/> Vehicle Repair | <input type="checkbox"/> Carpentry & Furniture Works | <input type="checkbox"/> Electrical Works |
| <input type="checkbox"/> Welding Works | <input type="checkbox"/> Plumbing Works | <input type="checkbox"/> Heating, Ventilating, Air conditioning & Refrigeration |
| <input type="checkbox"/> Machining works
(lathe, shaper, drill press, etc.) | <input type="checkbox"/> Instrumentation equipment
& Laboratory instrument | <input type="checkbox"/> Others (specify): _____ |

Brief Description of Repair and Maintenance

Request to repair cement storage room.

Materials/Supplies/Parts:

☐ Available

☐ Not Available

Filled in by PPO personnel

Part/Supplies/Materials Required	Manpower Requirement	Estimated hours/days to finished

Inspected
by:

PPO Maintenance

Checked
& Verified
by:

PPO Unit Head

Approved
by:

PPO Director