



Comfort Room Repair/Renovation/Construction Information Form

Dept./Office/Unit/ Center	Contact Person & Email Address	Building	No. of CRs for Inspection	Remarks
Department of Agronomy	Clemente N. Marañan Jr.	Head office	1	<ul style="list-style-type: none"> •Damage Toilet Flush •No exhaust fan installed •Ventilation Window
		Faculty and Staff Comfort room (Male)	1	<ul style="list-style-type: none"> •No PWD provision •Damage Toilet Flush •Need to repair the Tiles, Urinal and Electrical •Door knob needs repair
		Faculty and Staff Comfort room (Female)	1	<ul style="list-style-type: none"> •No PWD provision •Damage Toilet Flush •Door knob needs repair
		Communal Male Cr	1	<ul style="list-style-type: none"> •No PWD provision •Damage Toilet Flush •Electrical problems

Prepared by:


DIONESIO M. BAÑOC
DA, Dept. Head

Noted by:

BEATRIZ S. BELONIAS
Vice President for Academic Affairs