



OFFICE OF THE DIRECTOR FOR PHYSICAL PLANT

Visca, Baybay City, Leyte, PHILIPPINES Telefax: 1041(LOCAL)

Telefax: 1041(LOCAL)
Email: www.ppo.@vsu.edu.ph
Website: www.vsu.edu.ph

REPAIR AND MAINTENANCE REQUEST

Filled in by requesting party			Filled in by PPO				
Date filed : July 11, 2022 Building/Facility/			Date received	: _			
House No/ Apartment No./ Department			Received by	_	Name 8	Signature	
Location : Eco-FARMI			Designation/ Position	:			
Requesting party :			Maintenance control number	-			
Designation/ : Instructor I Position							
Please check and specify the nature of w	ork requested						
☐ Vehicle Repair		amentry & Fi	urniture Works	ПЕ	Electrical Works		
☐ Welding Works				Ø H	Heating, Ventilating, Air conditioning & Refrigeration		
Machining works (lathe, shaper, drill press, etc.)	equipment Others (specify):						
Materials/Supplies/Parts:	☐ Ava	ilable	5		Not Available		
Brief Description of Repair and Maintenance							
Cleaning of the Air conditioning unit.							
Filled in by PPO personnel							
Part/Supplies/Materials Required N		lanpower Re	equirement	E	Estimated hours	s/days to finished	
				-			
Filled in by the requesting party after the conduct of repair and maintenance							
Conducted by: PPO Personnel (Name & Signature) PPO Unit Checked & Verified by: PPO Head (Name & Signature)			ce Satisfaction	OVER-ALL RATING			
		_ 2 6	ot Satisfied lightly Satisfied	5 Sec. 10 10 10 10 10 10 10 10 10 10 10 10 10	- Poor - Good	☐ 2 Fair ☐ 4 Very Good	
		3 M	oderately Satisfied		- Good - Excellent	A Very Good	
			ery Satisfied	Comments & Suggestion			
			xtremely Satisfied		Comments	a ouggestion	
		Name	e and Signature				

Vision: Mission: