



## PHYSICAL PLANT SERVICE REQUEST FORM

Filled in by requesting party	
Date filed	: Feb. 15, 2011
Building/Facility/ House No/ Apartment No./ Department	: Protechnology
Location	: Upper Campus
Requesting party	: Kyza Mae Ramoneda
Designation/ Position	: OIC-Head

Filled in by PPO	
Date received	:
Received by	: Name & Signature
Designation/ Position	:
Maintenance control number	:

To be accomplished in three (3) copies

Please check and specify the nature of service request	
<input type="checkbox"/> Audio System (amplifier, speakers and microphones) With Lights? Yes. ___ No. ___ Setup Location: _____ Date & Time Needed: _____ Estimated Duration (hrs): _____	<input type="checkbox"/> Tent installation/s Setup Location: _____ No. of tent: _____ Tent size: _____
<input type="checkbox"/> Land preparation, plowing & harrowing Location/Area covered: _____ Estimated passing trip: _____	<input type="checkbox"/> Fabrication/s (new cabinets, furniture, metal works and other fabrications not considered as repair and maintenance)
<input type="checkbox"/> Site development, levelling, scrapping & backfilling Location: _____	<input checked="" type="checkbox"/> Installation/s (tarpaulin, signage, new lock & knobs & other installation not considered as repair and maintenance)
<input type="checkbox"/> Hauling (Construction materials, office equipment & etc.) From: _____ To: _____	<input type="checkbox"/> Machining works (lathe, shaper, drill press & etc.) <input type="checkbox"/> Others (specify): _____

Brief Description of Service Request
Installation of outlet for Airconditioner.

Service Conducted by	:	_____	Name & Signature
PPO Unit	:	_____	
Conformed by (Requesting Party)	:	_____	Name & Signature
Checked by (PPO Unit Head)	:	_____	Name & Signature

To be filled by the requesting party after service request conducted

Overall Service Satisfaction
1. Not Satisfied
2. Slightly Satisfied
3. Moderately Satisfied
4. Very Satisfied
5. Extremely Satisfied