



## OFFICE OF THE DIRECTOR FOR PHYSICAL PLANT

Visca, Baybay City, Leyte, PHILIPPINES

Telefax: 1041(LOCAL) Email: www.ppo.@vsu.edu.ph Website: www.vsu.edu.ph

## PHYSICAL PLANT SERVICE REQUEST FORM

REQUEST INFORMATIO	ON		
Filled in by requesting party		Filled in by PPO	
Date filed	: July 12, 2023	Date received	:
Building/Department	Advanced Research and Innovation Center	Received by	Name & Signature
Location	: Visayas State University	Designation/Position	:
Requesting party	: MA. THERESA P. LORET Name & Signature	O Request Reference Number	:
Designation/Position	: Director, ARI Center		
Contact no./Email	: mtploreto@vsu.edu.ph		
Audio System (a microphones) With Lights? Y Setup Location Date & Time N Estimated Dura Land preparation Location/Area of Estimated pass Site development backfilling Location: Hauling (Construequipment & etc.) From: Plans, Layouts a	uction materials, office	fabrications not considered a	furniture, metal works and other as repair and maintenance) nage, new lock & knobs & other s repair and maintenance) per, drill press & etc.) stallation)
and the likes)			
Brief Description of Service Request			
Fabrication of metal stand for Laboratory Incubator in EV-Biotech Laboratory, ARI Center -estimation of materials & cost -fabrication of stand			
ACCOMPLISHMENT			
Filled in by PPO Personnel Filled in by Requesting Party			
Conducted by :  Date & Time Started Date & Time Finished	PPO Maintenance Personnel (Name and Signature)	Service Satisfaction  1. Not Satisfied 2. Slightly Satisfied 3. Moderately Satisfied 4. Very Satisfied 5. Extremely Satisfied	OVER ALL RATING  1. Poor 2. Fair 4. Very  3. Good Good  5. Excellent  Comments & Suggestion
			Comments & Suggestion
Checked . ———————————————————————————————————	PPO Head/Director (Name and Signature)	Name &Signature	
Notes:			
		Designation/Position	