



OFFICE OF THE DIRECTOR FOR PHYSICAL PLANT

Visca, Baybay City, Leyte, PHILIPPINES Telefax: 1041(LOCAL) Email: www.ppo.@vsu.edu.ph Website: www.vsu.edu.ph

REPAIR AND MAINTENANCE REQUEST

Filled in by requesting party			Filled in by PPC			
Date filed : Building/Facility/ House No/ Apartment No./ Department Location : Requesting party :	Department of Ag VSU, Upper Campus Ruth O. Escas		Date received Received by Designation/ Position Maintenance	:Name	e & Signature	
Designation/ Position	Name & Signat <u>Department</u> H		control number			
	y the nature of work requeste					
☐ Vehicle Repair ☐ Welding Works ☐ Machining works (lathe, shaper, drill	I press, etc.)	Carpentry & F Plumbing Wor Instrumentatio & Laboratory i	on equipment	☐ Electrical Works ☐ Heating, Ventilating, Air conditioning & Refrigeration ☐ Others (specify):		
Materials/Supplies/Parts: Available Not Available						
Brief Description of Repair and Maintenance 1. Installation of Orbit fan at Utility room in the Department of Agronomy.						
Filled in by PPO personnel						
Part/Supplies/Materials Required		Manpower Re	equirement	Estimated hours/days to finished		
Conducted			illed in by the requesting party after the conduct of repair and maintenance			
bv:	PPO Personnel (Name & Signature)		ot Satisfied	OVER-A	LL RATING 2 Fair 4 Very Good	
Checked & Verified by: PPO Head (Name & Signature)		-	oderately Satisfied ery Satisfied xtremely Satisfied	☐ 5 Excellent Comments	s & Suggestion	
		Name	e and Signature			

Vision:

Mission:

A globally competitive university for science, technology, and environmental

and innovative technologies for sustainable communities and environment.

conservation.

Development of a highly competitive human resource, cutting-edge scientific knowledge

Page 1 of 1 FM-PPO-09

v0 02-28-2022