



## OFFICE OF THE DIRECTOR FOR PHYSICAL PLANT

Visca, Baybay City, Leyte, PHILIPPINES

Telefax: 1041(LOCAL) Email: www.ppo.@vsu.edu.ph Website: www.vsu.edu.ph

## REPAIR AND MAINTENANCE REQUEST

Filled in by requesting party		Filled in by PPO		
Date filed : August 4, 2022		Date received		
Building/Facility/ House No/ Apartment No./ Department	Eco-FARMI		Name	e & Signature
Location : VSU, Visca, Baybay Leyte		Designation/ Position	:	
	NA VILLAREMO e & Signature	Maintenance control number		
Please check and specify the nature of we	ork requested			
☐ Vehicle Repair	☐ Carpentry &	Furniture Works	☐ Electrical Wo	
☐ Welding Works	orks	Heating, Vent	tilating, Air & Refrigeration	
☐ Machining works (lathe, shaper, drill press, etc.) ☐ Instrumentation equipment & Laboratory instrument			Others (speci	
Materials/Supplies/Parts:  Available  Not Available				
Brief Description of Repair and Maintenance				
Cleaning/Maintenance of Air-conditioning unit of Eco-FARMI.				
Filled in by PPO personnel				
Part/Supplies/Materials Required Manpo		Requirement	Estimated hours/days to finished	
Filled in by the requesting party after the conduct of repair and maintenance				
Conducted PPO Personi	nel Serv	rice Satisfaction	OVER-ALL RATING	
by: (Name & Signa		Not Satisfied	☐ 1 Poor	☐ 2 Fair
PPO Unit	2	2. Slightly Satisfied	☐ 3 Good	☐ 4 Very Good
		B. Moderately	5 Excellent	4527
Checked & Verified by: PPO Head		Satisfied 4. Very Satisfied	Comments & Suggestion	
(Name & Signa	ture)	5. Extremely Satisfied	Comment	is a oaggestion
	Nan	ne and Signature		

Vision: Mission: