



OFFICE OF THE DIRECTOR FOR PHYSICAL PLANT

Visca, Baybay City, Leyte, PHILIPPINES Telefax: 1041(LOCAL) Email: www.ppo.@vsu.edu.ph Website: www.vsu.edu.ph

PHYSICAL PLANT SERVICE REQUEST FORM

Filled in by requesting party	Filled in by PP	0				
Date filed :	April 05, 2022	Date received	:			
Building/Facility/ House No/ Apartment No./ Department	Tuklas Lunas Development Center	Received by	Received by Name & Signature			
Location :	ARI Center	Designation/ Position	:			
Requesting party :	Jo Jane D. Atok	Document control number	:			
Designation/ Position :	Instructor I					
Please check and specify the nature of service request						
Audio System (amplifier microphones) With Lights? Yes Setup Location: Date & Time Needed:	No	Tent installation/s Setup Location: _ No. of tent: Tent size:				
Estimated Duration (h Land preparation, plowing	rs):	Fabrication/s (new	cabinets, furniture, monsidered as repair and			
Estimated passing trip:	Estimated passing trip: inst			tallation/s (tarpaulin, signage, new lock & knobs & other tallation not considered as repair and maintenance)		
backfilling	_					
Location:	Location: Landscaping (Design and Installation)					
Hauling (Construction mequipment & etc.)	Hauling (Construction materials, office equipment & etc.)			cation/Area covered:		
From: To: Other/s (Specify) : Plumbing services Plans, Layouts and Estimates (Drafting, floor plan/s, material & cost estimate, site inspection and the likes)						
Brief Description of Service Request						
Install hand-held bidet.	Brief Bescription	or octation reques				
Filled in by the requesting party after the conduct of service request				request		
Conducted ————	Servi	Service Satisfaction OVER-ALL RATING		L RATING		
by: PPO Per (Name & S		lot Satisfied	☐ 1 Poor	☐ 2 Fair		
PPO Unit	□ 2. 5	Slightly Satisfied	☐ 3 Good	☐ 4 Very Good		
	3. N	Moderately Satisfied	☐ 5 Excellent			
Checked & Verified by: PPO Heac (Name & S	I/Director □ 5. F	ery Satisfied extremely Satisfied	Comments	& Suggestion		
,		e and Signature	-			